



CODE ENFORCEMENT BOARD HEARING AGENDA

JANUARY 24, 2017 9:00 AM

CITY COMMISSION MEETING ROOM - CITY HALL 100 N ANDREWS AVENUE FT. LAUDERDALE, FL 33301

CODE ENFORCEMENT BOARD

Code of Ordinances: Sec. 11-3.

PURPOSE: Hear and decide cases in which violations are alleged of any provision of the Florida Building Code, Broward County Amendments and violations of the Code of Ordinances of the City of Fort Lauderdale when alleged together with a violation of the Florida Building Code.

Note: If any person decides to appeal any decision made with respect to any matter considered at this public meeting or hearing he/she will need a record of the proceedings and for such purpose, he/she may need to ensure that a verbatim record of the proceedings is made, which record includes the testimony and evidence upon which the appeal is to be based.

Board Members: Patrick McGee, **Chair •** Mark Booth, **Vice Chair •** Joan Hinton • Howard Nelson • Lakhi Mohnani • Peter Cooper • Robert Smith (alternate) • Michael Madfis (alternate) • **Board Attorney:** Bruce Jolly

TWO OR MORE FORT LAUDERDALE CITY COMMISSIONERS OR MEMBERS OF A CITY OF FORT LAUDERDALE ADVISORY BOARD MAY BE IN ATTENDANCE AT THIS MEETING.

HEARING SCHEDULED

CASE NO: CE14060871
CASE ADDR: 2221 SW 28 WAY
OWNER: CRISCIONE, GEORGE J

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

NO PERMIT OR EXPIRED PERMITS FOR WORK IN PROGRESS OR ALREADY DONE. THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS.

- 1. NEW WINDOWS AND DOORS WERE PLACED ON THE DWELLING WITH A VOID PERMIT FROM 2006.
- 2. MECHANICAL WORK HAS BEEN DONE WITH AN APPLIED AND ONE VOIDED PERMIT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE16011256
CASE ADDR: 1255 SW 15 AV
OWNER: THOMAS, GEORGE M

INSPECTOR: JOSE ABIN

VIOLATIONS: 9-259

THE DWELLING DOES NOT MEET THE MINIMUM HOUSING STANDARDS FOR THE CITY OF FORT LAUDERDALE.

- 1. THE WALLS ARE UNCOVERED.
- 2. ELECTRICAL AND PLUMBING HAS BEEN REMOVED AND ARE INOPERABLE.
- 3. ELECTRICAL HAS BEEN REMOVED WITHOUT PERMITS AND MAY POSE ELECTRICAL HAZARDS.
- 4. THE ROOF IS SAGGING AND LEAKING AND MAY POTENTIALLY COLLAPSE CAUSING BODILY INJURY TO ITS OCCUPANTS.

FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. INTERIOR REMODELING WORK. WALLS HAVE BEEN UNCOVERED IN THE LIVING ROOM KITCHEN AREAS. IT HAS NOT BEEN REBUILT AS OF THIS DATE.
- 2. PARTS OF THE ROOF STRUCTURE HAVE BEEN REBUILT WITHOUT SUBMITTING THE REQUIRED DOCUMENTS FROM A DESIGN PROFESSIONAL.

FBC(2014) 105.3.1.4.10

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. RE-ROOFING WORK HAS COMMENCED AND PARTS OF THE ROOF HAS BEEN DRIED IN.

FBC(2014) 105.3.1.4.15

ALTERATIONS, REPLACEMENT OR REPAIR OF EXTERIOR OPENINGS TO THE BUILDING ENVELOPE WILL REQUIRE PERMITS. THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. WINDOWS AND DOORS HAVE BEEN REPLACED WITHOUT SUBMITTING THE REQUIRED PRODUCT APPROVALS TO MEET HIGH VELOCITY HURRICANE ZONE STANDARDS FOR OPENING PROTECTION.

FBC(2014) 105.3.1.4.3

THIS BUILDING HAS BEEN ALTERED AND DEMOLITION WORK HAS BEEN PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. COMPLETE INTERIOR DEMOLITION HAS BEEN PERFORMED PRIOR TO OBTAINING THE REQUIRED PERMITS.
 - A. ELECTRICAL COMPONENTS HAVE BEEN REMOVED.
 - B. WALL AND WALL COVERING HAS BEEN REMOVED.
 - C. PLUMBING COMPONENTS HAVE BEEN REMOVED.
 - D. MECHANICAL COMPONENTS HAVE BEEN REMOVED.
 - E. ROOF STRUCTURES HAVE BEEN REMOVED.

FBC(2014) 105.3.1.5

WHERE APPLICABLE PERMIT REQUIREMENTS MUST HAVE SUPPORTING DOCUMENTATION FROM A QUALIFIED DESIGN PROFESSIONAL.

SUBMIT 2 SETS OF DRAWINGS/PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR.

MODIFICATIONS MADE PRIOR TO OBTAINING THE REQUIRED PERMITS MAY BE REQUIRED TO BE UNCOVERED FOR INSPECTIONS AND/OR CERTIFIED BY A LICENSED DESIGN PROFESSIONAL SOLELY AT THE DISCRETION OF THE BUILDING OFFICIAL. THIS INCLUDES BUT IT IS NOT LIMITED TO, ALL WALL STRUCTURES, ROOF STRUCTURES, ELECTRICAL SYSTEM, PLUMBING SYSTEM AND MECHANICAL SYSTEMS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 115.1

A STOP WORK WAS ISSUED.

STOP WORK ORDER ISSUED SINCE WORK IS ONGOING WITHOUT THE REQUIRED PERMITS. VIOLATION OF STOP WORK ORDER IS SUBJECT TO THE MAXIMUM PENALTIES AS OUTLINED UNDER THIS SECTION OF THE FLORIDA BUILDING CODE.

FBC(2014) 116.2.1.3.1

THIS BUILDING IN ITS PRESENT CONDITION DOES NOT MEET THE CRITERIA OF THE FLORIDA BUILDING CODE FOR MINIMUM MAINTENANCE STANDARD AND THE FORT LAUDERDALE MINIMUM HOUSING CODE AND IT MUST BE REPAIRED BY THE OWNERS OR DEMOLISHED:

WORK COMMENCED AND/OR COMPLETED PRIOR TO OBTAINING THE REQUIRED PERMITS IS DEEMED AS UNSAFE AND SUBJECT TO HAVE THE STRUCTURE BOARDED UP AND/OR DEMOLISHED UNDER THIS SECTION OF THE FLORIDA BUILDING CODE.

CASE NO: CE16020033
CASE ADDR: 315 SE 11 AV
OWNER: ATLANTIC LOFT LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. COMMENCED THE ILLEGAL CONSTRUCTION OF AN ATTACHED EXTERIOR LAUNDRY CLOSET ON LEFT ELEVATION OF STRUCTURE.

FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, SOLAR PANELS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED THE PLUMBING SYSTEM.

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED PLUMBING SUPPLY AND WASTE LINES TO SERVICE ILLEGALLY CONSTRUCTED LAUNDRY CLOSET.

FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING ELECTRICAL COMPONENTS THAT MAY INCLUDE SWITCHES, OUTLETS, ELECTRICAL FIXTURES, BREAKER/PANEL BOXES, METER BASES, WIRES, REWIRING AND OTHER ELECTRICAL COMPONENTS CONNECTED TO THE ELECTRICAL SYSTEM.

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED ELECTRICAL CIRCUITS TO SERVICE ILLEGALLY CONSTRUCTED LAUNDRY CLOSET. INCLUDES 220V CIRCUIT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16032362 CASE ADDR: 1851 NW 28 AV

OWNER: HANSBERRY, ANTOINETTE WALKER

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO: 1. INTERIOR REMODELING. RECONFIGURING WALLS.

2. KITCHEN AND BATHROOM REMODELING AND ALTERATIONS.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. ALTERING PLUMBING SYSTEMS.
- 2. INSTALLING SINKS AND FIXTURES.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. ALTERING ELECTRICAL SYSTEM.
- 2. INSTALLING ELECTRICAL FIXTURES, SWITCHES AND OUTLETS.

FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE HEREBY THE RESERVE THE AUTHORITY TO SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16040814
CASE ADDR: 2660 NW 21 ST
OWNER: SIP REALTY 1B LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. INTERIOR FIRE RESTORATION WORK WITHOUT A PERMIT.
- 2. COMPLETE INTERIOR REMODEL.
- 3. RESTORED WALL FRAME AND INSTALLED DRYWALL.
- 4. CLOSED WINDOWS OPENINGS WITH WOOD FRAMING AND CMU UNITS.
- 5. REMODELED KITCHEN AND BATHS.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

- 1. ILLEGALLY INSTALLED NEW MECHANICAL CONDENSOR UNIT.
- 2. ILLEGALLY INSTALLED NEW MECHANICAL EVAPORATOR UNIT.
- 3. ILLEGALLY RESTORED AIRCONDITIONING DUCTWORK.
- 4. WILL REQUIRE ALL BATHROOMS TO BE MECHANICALLY VENTED.

FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

- 1. ILLEGALLY INSTALLED NEW DOORS EXTERIOR AND INTERIOR.
- 2. ILLEGALLY INSTALLED NEW WINDOWS.

FBC(2014) 105.3.1.4.18

THE FOLLOWING DESCRIBED WORK REQUIRES A FENCE PERMIT AND INSPECTIONS:

- 1. PREXISTING FENCE WAS NOT PERMITTED AND ILLEGAL.
- 2. NEW SECTION OF FENCE WITH GATE AT REAR OF PROPERTY ILLEGALLY REPLACED.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. ILLEGALLY INSTALLED NEW SINKS IN KITCHEN AND BATH.
- 2. ILLEGALLY INSTALLED NEW FAUCETS IN KITCHEN AND BATHS.
- 3. ILLEGALLY INSTALLED NEW WATER SPIGOTS.
- 4. ILLEGALLY INSTALLED NEW WATER LINES.
- 5. ILLEGALLY INSTALLED NEW WASDTE LINES.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. ILLEGALLY INSTALLED NEW LIGHTING FIXTURES.
- 2. ILLEGALLY INSTALLED NEW SWITCHES AND OUTLETS.
- 3. ILLEGALLY INSTALLED NEW 220 OUTLETS FOT DRYER AND STOVE.
- 4. ILLEGALLY INSTALLED NEW ELECTRICAL WIRING FOR MECHANICAL SYSTEM.
- 5. ILLEGALLY IESTORED WIRING AFTER FIRE DAMAGE.
- 6. ILLEGALLY LOW VOLATGE WIRING FOR MECHANICAL THERMOSTAT.

FBC(2014) 105.3.1.5

SUBMIT 2 SETS OF "AS BUILT" ARCHITECTURAL DRAWINGS/PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 111.1.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

THIS DWELLING WAS DEEMED UNSAFE FOR HUMAN OCCUPANCY BY THE FIRE DEPARTMENT AND BUILDING DEPARTMENT AFTER IT WAS DESTROYED BY FIRE. IT HAS BEEN ILLEGALLY RESTORED WITH THE INTENT OF HAVING IT RE-OCCUPIED WITHOUT OBTAINING THE REQUIRED RE-ISSUANCE OF A CERTIFICATE OF OCCUPANCY DEEMING THE DWELLING SAFE AND HABITABLE FOR HUMAN OCCUPANCY.

CASE NO: CE16041244
CASE ADDR: 415 NW 7 ST

OWNER: TRUST NO 413-415

LAND TRUST SERVICE CORP TRSTEE

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.3.1.4.18

THE FOLLOWING DESCRIBED WORK REQUIRES A FENCE

PERMIT AND INSPECTIONS:

1. INSTALLED FENCE ON PERIMETER OF PROPERTY.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16062114 CASE ADDR: 3316 NE 18 ST

OWNER: WILLIAMS, GERARD S & JULIE C

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.3.1.4.3

THE FOLLOWING DESCRIBED WORK REQUIRES A DEMOLITION

PERMIT AND INSPECTIONS:

1. INTERIOR DEMOLITION INCLUDING BUILDING, MECHANICAL, ELECTRICAL AND PLUMBING.

FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE MAY

REQUIRE SITE INSPECTIONS PRIOR TO THE APPROVAL AND

ISSUANCE OF ALL AND ANY PERMITS AND/OR

DETERMINATION OF COMPLIANCE WITH THE FLORIDA

BUILDING CODE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16062316

CASE ADDR: 772 W EVANSTON CIR BLUE SKY DESIGN CORP

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.3.1.4.10

THE FOLLOWING DESCRIBED WORK REQUIRES A ROOF

PERMIT AND INSPECTIONS:

1. REMOVED TILE ROOF AND RE-ROOFED WITH ARCHITECTURAL SHINGLES. SIGNIFICANT PORTIONS OF THE ROOF STRUCTURE HAS BEEN REPLACED.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. REPAVED DRIVEWAY.

CASE NO: CE16081196

CASE ADDR: 2642 BARBARA DR OWNER: M100 HOLDINGS LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. CONSTRUCTING FACADE OF 26 GAUGE STEEL AT FRONT ELEVATION.
- 2. KITCHEN AND BATH REMODEL WITH AN APPLIED FOR PERMIT. PERMIT WAS NOT ISSUED.

STOP WORK ORDER POSTED.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

1. INSTALLATION OF PLUMBING FIXTURES FOR KITCHEN AND BATH REMODEL.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

1. INSTALLATION OF ELECTRICAL FIXTURES AND OUTLETS FOR KITCHEN AND BATH REMODEL.

OUTLETS: REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH 406.4 (D)(1) THRU (D)(6).
GFIS REQUIRED AS PER NEC 108.8.
OUTLET SPACING AS REQUIRED UNDER NEC 210.52.

R314.3.1 ALTERATIONS, REPAIRS AND ADDITIONS: WHEN ALTERATIONS, REPAIRS OR ADDITIONS REQUIRING A PERMIT OCCUR, THE INDIVIDUAL DWELLING UNIT SHALL BE EQUIPPED WITH SMOKE ALARMS LOCATED AS REQUIRED FOR NEW DWELLINGS.

FBC(2014) 105.3.1.4.10

THE FOLLOWING DESCRIBED WORK REQUIRES A ROOF PERMIT AND INSPECTIONS:

1. RE-ROOFING OF THE STRUCTURE.

FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF DOORS WITH AN APPLIED FOR PERMIT.
- 2. REMOVAL OF ACCORDION SHUTTERS AND INSTALLATION OF WINDOWS.

FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE MAY REQUIRE SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16091372
CASE ADDR: 520 NW 23 AVE
OWNER: YAFLAG LLC
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:
1. CLOSED EXTERIOR DOOR OPENING AT KITCHEN.

FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

1. REPLACE WINDOWS.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

1. REPLACEMENT OF ELECTRICAL PANEL AND OUTLETS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16090438
CASE ADDR: 633 SW 6 AV
OWNER: LG ASSETS LLC
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

THE FOLLOWING MANNER, BUT NOT LIMITE

1. NEW PORCH WITH STAIRS.

NEW DECK.
 NEW PAVERS.

FBC(2014) 105.3.1.4.18

THE FOLLOWING DESCRIBED WORK REQUIRES A FENCE PERMIT AND INSPECTIONS:

1. REPLACE FENCING AND INSTALLED GATES.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16110799
CASE ADDR: 630 NW 14 AV
OWNER: WHEELER, ALMA T

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 1029.4

1. INSTALLED PERMANENT GRILL OVER WINDOWS BLOCKING THE EMERGENCY ESCAPE AND RESCUE OPENINGS.

FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. PERMANANETLY PLACED GRILLS OVER WINDOWS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16120747

CASE ADDR: 800 NW 11 AVE

OWNER: 800 NW 11 AVE LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 1013.4

- 1. OPENING ON GUARDRAILS EXCEED THE MAXIMUM ALLOWABLE UNDER THE SECTIONS OF THIS CODE OF 4 INCHES.
- 2. STAIR RAILING ON WEST SIDE OF BUILDING HAS
- 3. THIS IS AN EXIGENT LIFE AND SAFETY HAZARD THAT IMMEDIATE ATTENTION IS REQUIRED TO MAKE SAFE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

._____

CASE NO: CE15102473 CASE ADDR: 1811 NW 27 TER

OWNER: HIRSCH CONSULTING LLC

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS.

- 1. HURRICANE SHUTTERS AND WINDOWS WERE REMOVED AND NEW IMPACT WINDOWS WERE INSTALLED IN THE OPENINGS.
- 2. THE ENCLOSED CARPORT FOR STORAGE IS BEEN USED AS LIVING SPACE W/O A CHANGE OF USE (CO)
- 3. THE DRIVEWAY WAS DONE WITH A VOIDED PERMIT AND TODAY'S REMAINS WORK W/O PERMIT.

FBC(2014) 105.3.1.4.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: 1. THE CENTRAL A/C WAS REPLACED WITHOUT PERMIT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE16051262 CASE ADDR: 1103 NW 7 TER

OWNER: BOWDEN RESIDENCES CENTRAL LLC

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2010) 105.1

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN

PROGRESS OR WORK COMPLETED.

1. SHED INSTALLED.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16080490 CASE ADDR: 3761 SW 1 ST

OWNER: MARQUEZ, YAQUELINE INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 101.4.4.1.1

1. THE FRONT YARD HAS BEEN COMPLETELY PAVED OVER RAIN WATER NOW FLOWING INTO THE STREET.

FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED IN THE FOLLOWING MANNER:

- 1. THE CARPORT HAS BEEN ENCLOSED CREATING ADDITIONAL LIVING SPACE.
- 2. AN ALUMINUM ROOF HAS BEEN INSTALLED ON THE WEST SIDE OF THIS PROPERTY.
- 3. THE FRONT YARD OF THIS PROPERTY HAS BEEN PAVED OVER.
- 4. A STORAGE SHED HAS BEEN INSTALLED AT THE REAR OF THE PROPERTY.

FBC(2014) 105.3.1.4.15

1. WINDOW INSTALLED IN THE ENCLOSING WALL.

FBC(2014) 105.3.1.4.18

1. ALUMINUM FENCE INSTALLED AROUND THE FRONT OF THE PROPERTY WITH DRIVE GATES.

FBC(2014) 105.3.1.4.5

1. ELECTRICAL CIRCUITS HAVE BEEN ADDED TO THE ENCLOSURE.

FBC(2014) 110.2

ACCESS TO PROPERTY BOTH INSIDE AND OUT REQUIRED TO DETERMIN IF ADDITIONAL VIOLATIONS EXIST.

FBC(2014) 110.6

REQUIRED INSPECTIONS FOR THE WORK COVERED IN THIS CASE MUST BE COMPLETED.

CASE NO: CE16080727 CASE ADDR: 5631 NE 16 AV

OWNER: GERBRACHT, CHRISTINE M

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2014) 105.1

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN

PROGRESS OR WORK COMPLETED.

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. PARTIAL ROOF INSTALLED.

2. AWNING INSTALLED.

FBC(2014) 105.3.1.4.10

THE FOLLOWING DESCRIBED WORK REQUIRES A ROOF PERMIT AND INSPECTIONS:

1. PARTIAL ROOF INSTALLED ON THE NORTH ELEVATION OF THE PROPERTY.

FBC(2014) 105.3.1.4.8

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. AWNING INSTALLED ON DRIVEWAY ANCHORED TO A WOOD STRUCTURE AND FASCIA.

FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE MAY REQUIRE SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16081835 CASE ADDR: 917 SE 6 CT

OWNER: SARJI, JASON & SAMANTHA

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. CARPOT ENCLOSED

2. NEW GARAGE DOOR INSTALLED

FBC(2014) 105.3.1.4.15

ALTERATIONS, REPLACEMENT OR REPAIR OF EXTERIOR OPENINGS TO THE BUILDING ENVELOPE WILL REQUIRE PERMITS. THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING

MANNER, BUT NOT LIMITED TO:

1. CARPOT ENCLOSURE

2. NEW GARAGE DOOR INSTALLED

CASE NO: CE16090592

CASE ADDR: 600 BREAKERS AVE
OWNER: SUNSCAPE GROUP LLC
INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. NEW PERGOLA INSTALLED BETWEEN THE TWO BUILDINGS.
- 2. NEW DECORATIVE WOODEN WALL INSTALLED IN FRONT ELEVATION OF BUILDING.
- 3. INTERIOR DEMOLITIONS AND RENOVATIONS.

FBC(2014) 105.3.1.4.1

THE ERECTION OR CONSTRUCTION OF ANY BUILDING OR STRUCTURE, THE ADDING TO, ENLARGING, REPAIRING, IMPROVING, ALTERING, COVERING OR EXTENDING OF ANY BUILDING OR STRUCTURE.

1. ONGOING INTERIOR RENOVATION.

FBC(2014) 105.3.1.4.19

THE INSTALLATION, ALTERATION OR REPAIR OF ANY SCREEN ENCLOSURE.

1. NEW DECORATIVE WOOD WALL IN FRONT ELEVATION OF BUILDING.

FBC(2014) 105.3.1.4.8

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. WOOD PERGOLA INSTALLALLED BETWEEN THE TWO BUILDINGS

CASE NO: CE16090624

CASE ADDR: 1421 NW 3 AV

OWNER: WSC TRUST I LLC

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ADDITIONAL ROOMS ADDED TO BACK OF HOME.

FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

1. TWO NEW BACK DOORS INSTALLED.

FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS BUT NOT LIMITED TO:

COMMENCING ELECTRICAL ALTERATIONS AND MODIFICATIONS PRIOR TO OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO THE INSTALLATION OF NEW ELECTRICAL PANEL, LIGHT FIXTURES, WALL OUTLETS, SWITCHES, AC SUPPLY AND METER BASE.

ALL ELECTRICAL ALTERATIONS MODIFICATIONS AND REPAIRS UNDER THE SECTION OF THIS CODE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16090813 CASE ADDR: 914 SE 2 CT

OWNER: MOORMAN PROPERTIES III LLC

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO: 1. NEW WOOD STRUCTURE WITH ROOF INSTALLED.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16090940 CASE ADDR: 2416 NE 26 TER

OWNER: STOOSHINOFF, DOUGLAS

SALA, EMMANUELLE

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. NEW WOOD FENCE INSTALLED.

2. NEW PAVERS BRICKS INSTALLED CONNECTING DRIVEWAY AND FENCE GATE.

FBC(2014) 105.3.1.4.18

THE INSTALLATION, ALTERATION OR REPAIR OF ANY FENCE:

1. NEW WOOD FENCE INSTALLED.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16091127
CASE ADDR: 1531 SW 26 ST
OWNER: SKY MOTEL INC
INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2014) 105.1

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN

PROGRESS OR WORK COMPLETED:

1. BATHROOM REMODELED IN ROOM #37.

2. WINDOW OPENING CLOSED.

FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

1. WINDOW OPENING CLOSED.

FBC (2014) 105.3.1.4.4

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, SOLAR PANELS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED THE PLUMBING SYSTEM.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

1. NEW VANITY AND FAUCETS INSTALLED

CASE NO: CE16041977
CASE ADDR: 1511 NW 11 PL

OWNER: 2771 LLC

INSPECTOR: FRANK ARRIGONI

VIOLATIONS: FBC (2014) 105.1

THE STRUCTURES ON THIS PROPERTY HAVE BEEN ALTERED WITHOUT PERMIT IN THE FOLLOWING MANNER:

- 1. WINDOWS AND EXTERIOR DOORS HAVE BEEN REPLACED.
- 2. GLASS BLOCK HAS BEEN INSTALLED IN PLACE OF THE BATHROOM WINDOW.
- 3. NEW SINK AND TOILET INSTALLED IN THE BATHROOM.
- 4. THE KITCHEN HAS BEEN REMODELED WITH ELECTRICAL OUTLETS AND DISHWASHER ADDED. KITCHEN SINK REPLACED.
- 5. THE WATER HEATER HAS BEEN REPLACED.
- 6. PLUMBING AND ELECTRICAL HAS BEEN ADDED FOR A WASHER AND DRYER IN THE UTILITY ROOM.
- 7. A CENTRAL A/C SYSTEM HAS BEEN INSTALLED.
- 8. ELECTRICAL SERVICE HAS BEEN UPGRADED WITH AN OUTSIDE BREAKER PANEL.
- 9. THE SHED DOOR HAS BEEN REPLACED.
- 10. A WOOD FENCE IS INSTALLED ON THE WEST SIDE OF THE HOUSE.

CASE NO: CE16051684
CASE ADDR: 1447 NW 6 ST
OWNER: JAMES, LOUIS
INSPECTOR: FRANK ARRIGONI

VIOLATIONS: FBC(2014) 105.1

SENT TO THIS LOCATION BY SUPPERVISOR GEORGE OLIVA AT THE REQUEST OF COMMISSIONER MCKINZIE TO INVESTAGATE WORK W/O PERMITS.

ON THE NW CORNER OF THE PROPERTY I FOUND A RECENTLY

- 1. INSTALLED CHAINLINK FENCE ENCLOUSER.
- 2. INSIDE NEW WATER LINES, SANITARY LINE AND SINK HAVE BEEN INSTALLED.
- 3. ELECTRICAL OUTLETS ARE BEING INSTALLED.
- 4. A NEW COUNTER IS BEING INSTALLED AND IT APPEARS PARTITIONS HAVE BEEN ALTERED OR ADDED.
- 5. ALL LIGHT FIXTURES IN THE ACOUSTICAL CEILING HAVE BEEN CHANGED.

NO PERMITS CAN BE FOUND FOR THIS WORK (ELECTRICAL AND PLUMBING PERMITS HAVE BEEN ISSUED. NO PERMIT FOR DUMPSTER INCLOSURE)

CASE NO: CE16071518
CASE ADDR: 5405 NE 22 TER
OWNER: KNEZEVIC, ANA

KNEZEVICH, DAVID

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. ALTERATIONS AND REMODELING PERFORMED WITHOUT THE REQUIRED PERMITS AND OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE

IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16100031

CASE ADDR: 2841 N OCEAN BLVD # 702

OWNER: ALALOUF, RICHARD H

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

INCLUDES BUT IS NOT LIMITED TO:

1 INTERIOR ALTERATIONS MADE SUC

1. INTERIOR ALTERATIONS MADE SUCH AS KITCHEN AND BATHROOM REMODELING INCLUDING ELECTRICAL AND PLUMBING WITHOUT THE REQUIRED PERMITS AND OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC (2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16110320

CASE ADDR: 2841 N OCEAN BLVD # 1102 OWNER: SANGERMANO, ROBERT J

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. INTERIOR ALTERATIONS MADE SUCH AS KITCHEN AND BATHROOM REMODELING INCLUDING ELECTRICAL AND PLUMBING WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16110323

CASE ADDR: 2841 N OCEAN BLVD # 1007 OWNER: MILLER, GUILLERMO & RUTH

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. INTERIOR ALTERATIONS MADE SUCH AS KITCHEN AND BATHROOM REMODELING INCLUDING ELECTRICAL AND PLUMBING WITHOUT THE REQUIRED PERMITS AND OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16111583 CASE ADDR: 5320 NW 9 AVE

OWNER: DEZER POWERLINE OUTPARCEL LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE EXTERIOR WALL ON THE EAST SIDE OF THE BUILDING HAVING AN OPENING CREATED, COLUMNS, HEADER BEAM, AND SLAB LOADING AREA FORMED AND POURED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16111679

CASE ADDR: 2455 NE 51 ST # E116

OWNER: COSTA, PETER A INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH

INCLUDES BUT IS NOT LIMITED TO:

1. INTERIOR ALTERATIONS MADE SUCH AS A KITCHEN REMODELING INCLUDING ELECTRICAL AND PLUMBING WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC (2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

CASE NO: CE16111737

CASE ADDR: 2029 N OCEAN BLVD # 202

OWNER: SALVAGGIO, TONY

TIATTO, PAOLA

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH

INCLUDES BUT IS NOT LIMITED TO:

1. KITCHEN AND BATHROOM REMODELING WITH ELECTRICAL AND PLUMBING WORK PERFORMED WITHOUT THE REQUIRED

PERMITS AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE

VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE

IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16120001

CASE ADDR: 2519 OKEECHOBEE LN
OWNER: GRANDILLO, CHRISTINE M

SHEFNER, FRANK

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. ALTERATIONS OF THE ELECTRICAL SYSTEM AND REPLACING THE ELECTRICAL SERVICE WITHOUT THE

REQUIRED PERMITS AND/OR INSPECTIONS.

FBC (2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE

IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16120003

CASE ADDR: 350 E DAYTON CIR OWNER: GARCIA, RICARDO INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. THE ILLEGAL SUBDIVISION OF THE HOUSE AND CREATING THREE SEPARATE STUDIO LIVING UNITS WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.
- 2. THERE IS ALSO A FENCE ACROSS THE FRONT OF THE PROPERTY INSTALLED WITHOUT THE REQUIRED PERMITS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS MADE WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC (2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16120100

CASE ADDR: 2678 MARATHON LN

OWNER: ACTION GLOBAL INVESTMENTS LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. DEMOLITION AND REMODELING THAT INCLUDES STRUCTURAL, ELECTRICAL, MECHANICAL AND PLUMBING WORK PERFORMED WITHOUT THE REQUIRED PERMITS AND/OR

INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

RETURN HEARING (OLD BUSINESS)

CASE NO: CE08070448
CASE ADDR: 1431 NW 11 PL

OWNER: DRAGOSLAVIC, GORAN

DRAGOSLAVIC, TERESA

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC (2007) 105.1

THE PROPERTY SUSTAINED MAJOR DAMAGE TO THE STRUCTURE AND THE INTERIOR CAUSED BY A FIRE BACK

ON JULY 7, 2008.

A STOP WORK ORDER WAS ISSUED ON JULY 11, 2011 FOR WORK IN PROGRESS. ALL THE REPAIRS WERE PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND

INSPECTIONS:

- 1. THE ELECTRICAL SYSTEM WAS DAMAGED AND IT HAS BEEN REPAIRED.
- 2. THE FAMILY ROOM CEILING RAFTERS WITH THE ROOF DECK WAS COMPLETELY BURNED AWAY. THEY HAVE BEEN REPLACED.
- 3. COMPLETE INTERIOR RESTORATION: ALL THE ELECTRICAL AND PLUMBING FIXTURES, THE DRYWALL ON THE CEILING AND WALLS, WITH ALL THE CABINETRY WERE REPLACED.
- 4. THE AIR CONDITIONING SYSTEM HAS BEEN REPLACED IN WHOLE OR IN PART FROM THE FIRE DAMAGE.

FBC(2007) 109.10

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

CASE NO: CE11061307 CASE ADDR: 2021 NE 59 ST

OWNER: LANE, CHRISTOPHER E & WENDY B

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC (2007) 105.1

THE BUILDING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT OBTAINING THE REQUIRED PERMITS:

1. THE GARAGE HAS BEEN ENCLOSED AND HAS BEEN

- CONVERTED TO LIVING SPACE.
- 2. THE GARAGE HAS BEEN ENCLOSED.
 3. WINDOWS HAVE BEEN INSTALLED.
- 4. INTERIOR FRAMING AND DRYWALL HAVE BEEN INSTALLED.

FBC(2007) 105.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. THE ENCLOSED GARAGE HAS BEEN AIR CONDITIONED.

FBC(2007) 105.4.4

THE PLUMBING SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. PIPING AND FIXTURES HAVE BEEN INSTALLED DURING THE GARAGE ENCLOSURE.

FBC(2007) 105.4.5

THE ELECTRICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. CIRCUITS HAVE BEEN ADDED/ALTERED DURING THE GARAGE ENCLOSURE.

FBC(2007) 109.10

WORK WAS PERFORMED AND/OR COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC(2007) 1612.1.2

THE ENCLOSED GARAGE OPENING, THE WINDOWS INSTALLED, AND THE AC UNIT, IF INSTALLED, HAVE NOT BEEN PROVEN TO SUFFICIENTLY WITHSTAND ESTIMATED OR ACTUAL IMPOSED DEAD, LIVE, WIND, OR ANY OTHER LOADS THROUGH THE PERMIT AND INSPECTION PROCESS.

CASE NO: CE15040555
CASE ADDR: 810 NE 4 AV
OWNER: R W L 4 INC
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC (2010) 105.1

THIS BUILDING WAS APPROVED TO BE USED AS A WAREHOUSE. IT HAS BEEN ALTERED AND IS BEING USED AS A NIGHT CLUB. THERE IS AN OPEN BAR AND IT IS NOW A VENUE FOR MUSIC/COMEDY SHOWS.

- 1. SEVERAL WOOD STAGES WERE BUILT AT THE REAR AND THE BAR AREA.
- 2. ELECTRICAL LIGHTS WERE HUNG OVER THE OPEN YARD AND THE USE OF ELECTRICAL EXTENSIONS CORDS SUPPLYING POWER TO THE STAGE AREA.
- 3. THERE IS A KITCHEN AREA. THEY ARE NOT APPROVED TO SELL FOOD. A PERMIT IS REQUIRED AS PER FBC 105.1.5.
- 4. THE PARKING LOT AND THE TWO EXISTING BATHROOMS ARE NOT THE STANDARD REQUIREMENT OF THE ADA OR THE FBC ACCESSIBILITY.

FBC (2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THIS BUILDING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION FOR GROUP M TO AN ASSEMBLY GOUP A-2 OR A-3; WITHOUT OBTAINING THE REQUIRED PERMITS FOR A CHANGE OF USE AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CASE NO: CE15041350 CASE ADDR: 1162 NW 9 TER

OWNER: MERSAN HOLDINGS LLC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

1. STRUCTURAL, PLUMBING AND ELECTRICAL ALTERATIONS ARE BEING DONE TO THE BUILDING. ALL THE WINDOWS

AND DOORS WERE REPLACED IN THE OPENINGS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITING AND INSPECTION PROCESS.

CASE NO: CE15102378

CASE ADDR: 680 TENNIS CLUB DR # 301

OWNER: LOPEZ, DENNIS R

LOPEZ, DENNIS A

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS.

- 1. WORK WITHOUT PERMIT IN PROGRESS, THE INTERIOR OF THE UNIT WAS GUTTED WITHOUT A DEMOLITION PERMIT.
- 2. RENOVATION ARE BEING DONE AS FRAMING, ELECTRICAL, PLUMBING AND MECHANICAL WITHOUT THE PROPER PERMITS AND INSPECTIONS, INCLUDING THE OPENINGS ON THE FIRE PARTITONS.
- 3. WINDOWS WERE REPLACED.
- 4. CENTRAL A/C IS BEING REPLACED AND THE DUCT WORK IS BEING ALTERED.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15101733

CASE ADDR: 1216 CHATEAU PARK DR

OWNER: S R SINGH ENTERPRISES LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ALTERATIONS BY ENCLOSING THE GARAGE OF THE STRUCTURE.

FBC(2014) 105.3.1.4.15

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. REPLACEMENT OF EXTERIOR DOORS AND WINDOWS WILL REQUIRE PERMITTING.

FBC (2014) 105.3.1.4.4

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED THE PLUMBING SYSTEM.

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. PLUMBING FIXTURES INCLUDING WATER HEATER.

FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING ELECTRICAL COMPONENTS THAT MAY INCLUDE SWITCHES, OUTLETS, ELECTRICAL FIXTURES, BREAKER/PANEL BOXES, METER BASES, WIRES, REWIRING AND OTHER ELECTRICAL COMPONENTS CONNECTED TO THE ELECTRICAL SYSTEM.

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE

FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. ELECTRICAL FIXTURES, SWITCHES AND OULETS.
- 2. CIRCUITRY FOR WATER HEATER.

FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE HEREBY RESERVE THE AUTHORITY TO SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE13051997
CASE ADDR: 1515 NW 7 AVE

OWNER: YUTHASUNTHORN, CHANCE

YUTHASUNTHORN, SIRILUK,

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THE SINGLE FAMILY DWELLING HAS BEEN ALTERED IN THE

FOLLOWING MANNER WITHOUT A PERMIT:
1. NEW WINDOWS HAVE BEEN INSTALLED.

- 2. A KITCHEN REMODELING PROJECT IS IN PROGRESS.
- 3. A BATHROOM REMODELING PROJECT IS IN PROGRESS.

FBC(2010) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED BY THE KITCHEN AND BATHROOM REMODELING WITHOUT A PERMIT.

FBC(2010) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED WITH THE KITCHEN AND BATHROOM REMODELING WITHOUT A PERMIT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14121358

CASE ADDR: 111 FLORIDA AVE OWNER: AGUERO, VANESSA

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. NEW KITCHEN CABINETS, AND EXTERIOR DOORS.
AS OF 12/02/2015 PERMITS HAVE NOT BEEN CLOSED,
INSPECTIONS NOT CALLED IN.

FBC(2010) 105.4.4

THE FOLLOWING WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

1. FIXTURES BEING CHANGED.

FBC(2010) 105.4.5

THE FOLLOWING WORK REQUIRES AN ELECRICAL PERMIT AND INSPECTIONS:

1. SWITCHES AND OUTLETS BEING CHANGED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15010368
CASE ADDR: 3811 SW 12 PL
OWNER: DAGUINDEAU, LOUIS

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INTERIOR REMODELING KITCHENS AND BATHS.

FBC(2010) 105.4.15

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. WINDOWS AND DOORS HAVE BEEN INSTALLED.

FBC(2010) 105.4.18

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. FENCE HAS BEEN INSTALLED.

FBC(2010) 105.4.4

ALTERING, REPAIRING, INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS. INSTALLATION AND MODIFICATION BUT NOT LIMITED TO:

1. KITCHENS AND BATHS

FBC(2010) 105.4.5

ALTERING, REPAIRING, INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS BUT NOT LIMITED TO:

1. NEW ELECTRICAL FIXTURES, OUTLETS AND SWITCHES.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

.-----

CASE NO: CE15010467
CASE ADDR: 1951 NE 51 ST
OWNER: RODELU LLC
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.4.11

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF AIR CONDITIONING UNITS WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF ELECTRICAL WIRING AND DEVICES TO POWER AIR CONDITIONING UNITS WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15041915
CASE ADDR: 1309 NW 15 CT
OWNER: DALL 2 LLC
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS:

- 1. ILLEGAL CONVERSION OF THE OPEN CARPORT INTO 1/1 RENTAL APARTMENT WITH AN EXTRA COOKING AREA AND A BATHROOM.
- 2. THE ELECTRICAL AND PLUMBING SYSTEM WAS ALTERED TO BUILD THE APARTMENT IN THE OPEN CARPORT THAT WAS ENCLOSED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15051829
CASE ADDR: 1804 NW 16 CT
OWNER: TUCHOW, TYLER
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. THE CARPORT HAS BEEN ENCLOSED.
- 2. PLUMBING, ELECTRICAL & MECHANICAL WORK HAVE BEEN DONE WITHIN THE ENCLOSED CARPORT FOR A BATHROOM AND WASHER AND DRYER.

FBC(2010) 105.4.5

THE ELECTRICAL IN THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ELECTRICAL SUPPLYING THE ENCLOSED CARPORT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2010) 111.1.1

USE AND OCCUPANCY. NO BUILDING OR STRUCTURE SHALL BE USED OR OCCUPIED, AND NO CHANGE IN THE EXISTING OCCUPANCY CLASSIFICATION OF A BUILDING OR STRUCTURE OR NATURE OR USE OR PORTION THEREOF SHALL BE MADE UNTIL THE BUILDING OFFICIAL HAS ISSUED A CERTIFICATE OF OCCUPANCY THERE FOR AS PROVIDED HEREIN. SAID CERTIFICATE SHALL NOT BE ISSUED UNTIL ALL REQUIRED ELECTRICAL, GAS, MECHANICAL, PLUMBING AND FIRE PROTECTION SYSTEMS, AND PROVISIONS OF FFPC HAVE BEEN INSPECTED FOR COMPLIANCE WITH THE TECHNICAL CODES AND OTHER APPLICABLE LAWS AND ORDINANCES AND RELEASED BY THE BUILDING OFFICIAL. ISSUANCE OF A CERTIFICATE OF OCCUPANCY SHALL NOT BE CONSTRUED AS AN APPROVAL OF A VIOLATION OF THE PROVISIONS OF THIS CODE OR OF OTHER ORDINANCES OF THE JURISDICTION.

CASE NO: CE15070786

CASE ADDR: 1437 NE 56 ST

OWNER: BRODETZKI, YUVAL

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THE BUILDING HAS BEEN ALTERED WITHOUT A PERMIT. IT HAS BEEN CONVERTED TO FIVE UNITS. APPROVED USE IS FOR A SINGLE UNIT FAMILY RESIDENCE.

FBC(2014) 105.3.1.4.11

THE MECHANICAL SYSTEM HAS BEEN ALTERED WITHOUT A PERMIT.

FBC(2014) 105.3.1.4.15
WINDOW AND DOOR INSTALLATIONS AND ALTERATIONS
WITHOUT A PERMIT

FBC(2014) 105.3.1.4.4

THE PLUMBING HAS BEEN ALTERED WITHOUT A PERMIT.

FBC(2014) 105.3.1.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED WITHOUT A PERMIT.

FBC(2014) 105.4.1.2

OWNER OF RECORD IS RESPONSIBLE TO ABIDE BY FLORIDA
BUILDING CODE AS OUTLINED IN FLORIDA STATUTES.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITING PROCESS.

FBC(2014) 111.4.1

PROPERTY IS A SINGLE FAMILY RESIDENCE APPROVED FOR SINGLE USE. THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF A SINGLE FAMILY TO A FIVEPLEX WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CASE NO: CE15080382 CASE ADDR: 2151 NW 29 TER

OWNER: KINGS, TERRY JR EST

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.3.1.4.3

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. AFTER FIRE, INTERIOR OF DWELLING HAS BEEN DEMOLISHED. WALL AND CEILING COVERINGS REMOVED.
- 2. ELECTRICAL AND PLUMBING FIXTURES HAVE BEEN ALTERED AND/OR REMOVED.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15082267
CASE ADDR: 1621 NW 2 AV
OWNER: BEAULY LLC
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. REMODELLED KITCHEN BY INSTALLATION OF NEW KITCHEN AND BATHROOM CABINETS WITHOUT A PERMIT.
- 2. INSTALLED EXTERIOR DOORS WITHOUT A PERMIT.

FBC(2014) 105.3.1.4.18

1. FENCE AND GATE WAS INSTALLED WITHOUT A PERMIT.

FBC(2014) 105.3.1.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. KITCHEN AND BATHROOM PLUMBING.

FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS. NOT LIMITED TO:

1. EXTERIOR LIGHTING AND OUTLETS. KITCHEN/BATHROOM OUTLETS

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15090546
CASE ADDR: 1829 SW 11 ST
OWNER: LANIGAN, THOMAS P

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. BATHROOM ALTERATIONS TO THE WALL STRUCTURE REQUIRING PERMIT.

FBC(2014) 105.3.1.4.17

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. GARAGE DOOR INSTALLATION REQUIRING A PERMIT.

FBC(2014) 105.3.1.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. PLUMBING FIXTURES REQUIRING A PERMIT

FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS. NOT LIMITED TO:

1. CHANGEOUT OF ELECTRICAL FIXTURES REQUIRING PERMIT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15091002 CASE ADDR: 1135 NW 7 AV

TIITF/HRS-YOUTH SERV

BROWARD CHILDRENS SHELTER

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. PAVED AND STRIPPED PARKING AREA WITHOUT

ACQUIRING THE REQUIRED PERMIT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE15102466 CASE ADDR: 2871 NW 18 CT PETUDO LLC OWNER:

ARRITITI TR

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

WORKING WITHOUT PERMITS, AS:

- 1. INTERIOR RENOVATIONS IN PROGRESS.
- 2. THE REAR FLATROOF DECK IS BEING REDONE WITHOUT PERMITS.
- 3. THE DWELLING WAS REROOF WITH A PERMIT 07010493 THAT WAS LEFT TO EXPIRE AND TODAY IS WORK WITHOUG
- 4. TWO OPENING WERE CUT ON THE GARAGE WALL AND TWO WINDOWS WERE PLACED ON IT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15101560
CASE ADDR: 3121 SW 20 CT
OWNER: BARNETTE, KYLE W

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.3.1.4.3

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. DEMOLITION OF ROOF.

FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS. INSTALLATION AND MODIFICATION BUT NOT LIMITED TO:

1.WATER HEATER MANUFACTURED IN JANUARY/2010 INSTALLED.

FBC (2014) 105.3.1.4.5

ALTERING, REPAIRING, INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS BUT NOT LIMITED TO:

1. ELECTRICAL FOR WATER HEATER.

FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE HEREBY RESERVE THE AUTHORITY TO SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15121156
CASE ADDR: 1115 NE 6 AV
OWNER: JONES, GLORIA M

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 111.1.1

THIS DWELLING HAS BEEN DAMAGED BY FIRE. FIRE RESTORATION HAS BEEN DONE WITHOUT PERMITS. CERTIFICATES FOR OCCUPANCY DEEMING THE STRUCTURE SAFE AFTER FIRE DAMAGE HAVE NOT BEEN ISSUED.

FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. FIRE RESTORATION.
- 2. STORM SHUTTER INSTALLATION.
- 3. REPAIRING OF SMOKE AND FIRE DAMAGED INTERIOR WALLS.
- 4. BUILT SHEDS WHICH ARE NOW IN THE SETBACK.
- 5. PERMITS WERE ALLOWED TO EXPIRE AND WORK IS NOW WORK WITHOUT PERMIT.

FBC(2014) 105.3.1.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. REPLACED FIRE DAMAGED DUCTWORK.
- 2. NEW SPLIT SYSTEM EQUIPENT REPLACED.
- 3. PERMIT EXPIRED BECOMING WORK WITHOUT PERMIT.

FBC(2014) 105.3.1.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. REPLACEMENT OF PLUMBING FIXTURES.
- 2. PERMIT EXPIRED AND IT IS NOW WORK WITHOUT PERMITS.

FBC(2014) 105.3.1.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. ELECTRICAL REPAIRS DUE TO FIRE DAMAGE.
- 2. PERMIT EXPIRED AND IT IS NOW WORK WITHOUT PERMIT.

FBC(2014) 105.3.2.1

THE FOLLOWING PERMITS WERE LEFT TO EXPIRE:

99070788 EXPIRED BSHUTTERST 1115 NE 06 AV JONES, GLORIA M STORM SHUTTERS

11120763 EXPIRED BALTR1M 1115 NE 6 AV JONES, GLORIA M SFR REPLACE SMOKE DAMAGED DRYWALL 1000 SQ FT

11120767 EXPIRED MDUCT 1115 NE 6 AV JONES, GLORIA M REPLACE DUCTS BP 11120763

11120768 EXPIRED ERESADD 1115 NE 6 AV JONES, GLORIA M ELECTRIC FOR REPAIR SMOKE DAMAGE BP 11120763

11120771 EXPIRED PFIXREPLAC 1115 NE 6 AV JONES, GLORIA M REPLACE FIXTURES BP 11120763

14091302 EXPIRED EMISCELL 1115 NE 6 AV JONES, GLORIA M ATF ELECTRICAL AS PER PLAN BP14120081

14120081 EXPIRED BALTR1M 1115 NE 6 AV JONES, GLORIA M ATF REPAIR FIRE DAMAGE

14120101 EXPIRED PFIXREPLAC 1115 NE 6 AV JONES, GLORIA M ATF REPLACE FIXTURES BP14120081

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 116.1.1

THIS BUILDING IN ITS PRESENT CONDITION DOES NOT MEET THE CRITERIA OF THE FLORIDA BUILDING CODE FOR MINIMUM MAINTENANCE STANDARD AND THE FORT LAUDERDALE MINIMUM HOUSING CODE. IT MUST BE REPAIRED BY THE OWNERS AND INSPECTED:

WORK COMMENCED AND/OR COMPLETED PRIOR TO OBTAINING THE REQUIRED PERMITS IS DEEMED AS UNSAFE UNDER THIS SECTION OF THE FLORIDA BUILDING CODE.

CASE NO: CE15121310

CASE ADDR: 4100 N FEDERAL HWY
OWNER: 4100 FEDERAL HWY LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. KITCHEN LAYOUT RECONFIGURED FROM ORIGINAL FLOORPLAN.
- 2. DINING ROOM LAYOUT CHANGED.
- 3. INSTALLED CANOPY ON NORTH SIDE OF BUILDING.
- 4. RECONFIGURED STORAGE AREAS.
- 5. BUILT A DECORATIVE STRUCTURE WITHIN THE DINING/BAR AREA.
- 6. 3 SIGNS INSTALLED USING THE EXISTING ELECTRICAL.

FBC(2014) 105.3.1.4.3

THIS BUILDING HAS BEEN ALTERED AND DEMOLITION WORK HAS BEEN PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. REMOVED BAR AREA AND SINKS.
- 2. REMOVED WALL SINKS AT ENTRY TO KITCHEN.

FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, SOLAR PANELS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED THE PLUMBING SYSTEM.

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ADDED NEW PLUMBING AND FIXTURES. PENETRATIONS THROUGH EXTERIOR WALL TO SERVICE NEW PLUMBING ALTERATIONS.

FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING

ELECTRICAL COMPONENTS THAT MAY INCLUDE SWITCHES, OUTLETS, ELECTRICAL FIXTURES, BREAKER/PANEL BOXES, METER BASES, WIRES, REWIRING AND OTHER ELECTRICAL COMPONENTS CONNECTED TO THE ELECTRICAL SYSTEM.

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ADDED NEW ELECTRICAL. NEW CONDUITS VISIBLE.
PENETRATIONS THROUGH EXTERIOR WALL TO SERVICE NEW
ELECTRICAL INSTALLATIONS. ELECTRICAL ALTERATIONS
TO THE BAR AREA.

FBC(2014) 105.3.1.4.11

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF THE MECHANICAL COMPONENTS AND/OR MODIFYING THE MECHANICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING CONDENSER UNITS, EVAPORATOR UNITS, DUCTWORK, ELECTRICAL COMPONENTS, THERMOSTATS, COOLING TOWERS, HEATERS, AND OTHER MECHANICAL COMPONENTS CONNECTED TO THE MECHANICAL SYSTEM.

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. STORAGE FREEZERS HAVE BEEN ALTERED.
- 2. NEW MECHANICAL INSTALLATION UNDER CANOPY ON NORTH SIDE OF BUILDING.

FBC(2014) 105.3.1.4.15

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLATION OF EXTERIOR DOORS AT NORTH SIDE OF BUILDING.

FBC(2014) 105.3.1.5

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS:

1. SUBMIT "AS BUILT" ARCHITECTURAL DRAWINGS AND THE SCOPE OF WORK COVERING ALL EXISTING STRUCTURES AND MODIFICATIONS FROM A CERTIFIED AND LICENSED DESIGN PROFESSIONAL ADDRESSING THE ENTIRE EXISTING STRUCTURE AND SYSTEMS.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16011458

CASE ADDR: 2307 N OCEAN BLVD OWNER: KERR-ROLLE, SWABY

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF MULTI-FAMILY TO ASSIGNED LIVING FACILITY WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT

FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

REMODELING OF STRUCTURE, INTERIOR AND EXTERIOR.

- 1. REMODELING INTERIOR WALL, REMOVING WALL COVERING AND REINSTALLING THROUGHOUT INCLUDING BATHROOMS, KITCHENS AND OTHER LIVING AREAS.
- 2. INSTALLED PERMANENT STRUCTURE ON EXTERIOR WALLS.

FBC(2014) 105.3.1.4.11

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF THE MECHANICAL COMPONENTS AND/OR MODIFYING THE MECHANICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING CONDENSER UNITS, EVAPORATOR UNITS, DUCTWORK, ELECTRICAL COMPONENTS, THERMOSTATS, COOLING TOWERS, HEATERS, AND OTHER MECHANICAL COMPONENTS CONNECTED TO THE MECHANICAL SYSTEM.

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- ADDING/ALTERING THE COOLING AND HEATING SYSTEM.
- 2. ALTERING KITCHEN AND BATHROOM EXHAUST SYSTEM.

FBC(2014) 105.3.1.4.15

ALTERATIONS, REPLACEMENT OR REPAIR OF EXTERIOR OPENINGS TO THE BUILDING ENVELOPE WILL REQUIRE PERMITS. THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. REPLACEMENT OF EXTERIOR DOORS AND WINDOWS.

FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, SOLAR PANELS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS CONNECTED THE PLUMBING SYSTEM.

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLATION OF PLUMBING FIXTURES INCLUDING TOILETS, FAUCETS, PLUMBING LINES, VALVES, WASTE LINES. PLUMBING ASSOCIATED WITH BATHROOM AND KITCHEN REMODELING.

FBC(2014) 105.3.1.4.5

ALTERING, REPAIRING, REMOVAL AND INSTALLATION OF ELECTRICAL COMPONENTS AND/OR MODIFYING THE ELECTRICAL SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS INCLUDING BUT NOT LIMITED TO INSTALLING, REMOVING AND REPLACING ELECTRICAL COMPONENTS THAT MAY INCLUDE SWITCHES,

OUTLETS, ELECTRICAL FIXTURES, BREAKER/PANEL BOXES, METER BASES, WIRES, REWIRING AND OTHER ELECTRICAL COMPONENTS CONNECTED TO THE ELECTRICAL SYSTEM.

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLATION AND REPLACEMENT OF FIXTURES, OUTLETS, SWITCHES, BREAKER PANELS AND DISCONNECTS.

FBC(2014) 105.3.1.5

SUBMIT DRAWINGS AND A SCOPE OF WORK COVERING STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR.

MODIFICATIONS MADE PRIOR TO OBTAINING THE REQUIRED PERMITS MAY BE REQUIRED TO BE UNCOVERED FOR INSPECTIONS AND/OR CERTIFIED BY A LICENSED DESIGN PROFESSIONAL SOLELY AT THE DISCRETION OF THE BUILDING OFFICIAL. THIS INCLUDES BUT IT IS NOT LIMITED TO, ALL WALL STRUCTURES, ROOF STRUCTURES, ELECTRICAL SYSTEM, PLUMBING SYSTEM AND MECHANICAL SYSTEMS.

FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE HEREBY THE RESERVE THE AUTHORITY TO SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

ONSITE INSPECTION WILL BE REQUIRED TO VERIFY PERMIT APPLICATION REQUIREMENTS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16012048

CASE ADDR: 2201 N OCEAN BLVD OWNER: HOTEL MOTEL INC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. INSTALLED HANDRAILS.

2. INSTALLED WOOD DECK.

FBC(2014) 105.3.1.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:
1. INSTALLED WATER HEATER.

FBC(2014) 105.3.1.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ELECTRICAL TO SERVICE WATER HEATER.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16021843 CASE ADDR: 1420 NE 15 AV

OWNER: BORRAS, ALEXANDRA L

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. BUILDING A WOOD FRAME CARPORT ONTO EXISTING DRIVEWAY.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16030296
CASE ADDR: 2370 NW 26 ST
OWNER: BENJAMIN, ERNST

BENJAMIN, ROSE MARIE

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. REPLACED ROOF DECKING WITH STRIPS OF 5 INCH PLYWOOD.
- 2. MODIFIED ROOF RAFTERS BY SCABBING PIECES OF WOOD.
- 3. STRUCTURAL REPAIRS TO ROOF STRUCTURE REQUIRING ENGINEERING.
- 4. CEILING DRYWALL COVER HAS BEEN REPLACED THROUGHOUT THE HOUSE.

FBC(2014) 105.3.1.5

SUBMIT TWO SETS OF DRAWINGS OR PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR. DOCUMENTS FROM DESIGN PROFESSIONAL REQUIRE ORIGINAL COPIES, SIGNED AND SEALED BY DESIGN PROFESSIONAL.

FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE MAY REQUIRE SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16030350
CASE ADDR: 1535 NW 10 AV

OWNER: WASHINGTON, JEANETTE

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.3.1.4.18

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. MODIFIED EXISTING FENCE FROM ORIGINAL APPROVED CONFIGURATION.

FBC(2014) 105.3.1.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED NEW PLUMBING AT BACK OF PROPERTY.

FBC(2014) 105.3.1.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. NEW ELECTRICAL 220V OUTLET.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16032109
CASE ADDR: 601 SW 17 ST
OWNER: C4NAVIGATOR LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS
BEEN CHANGED FROM THE ORIGINALLY PERMITTED
OCCUPANCY CLASSIFICATION OF TWO FAMILY DUPLEX TO A
5 FAMILY FIVEPLEX WITHOUT OBTAINING THE REQUIRED
PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE

BUILDING DEPARTMENT.

FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

1. INSTALLED NEW IMPACT WINDOWS AND DOORS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND OR COVERED UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16032371
CASE ADDR: 2327 SW 17 AVE
OWNER: JANDEBEUR, PATRICK

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:
1. BUILT SCREEN ENCLOSURE STRUCTURE AT BACK ELEVATION OF BUILDING.

2. CONSTRUCTION OF SCREEN ENCLOSURE STRUCTURE IN PROGRESS AT RIGHT ELEVATION OF BUILDING.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REOUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16040470 CASE ADDR: 605 SW 17 ST OWNER: C4NAVIGATOR LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF 2 FAMILY DUPLEX TO 3 FAMILY TRI-PLEX WITHOUT OBTAINING THE REOUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE

BUILDING DEPARTMENT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND

WINDOW PERMIT AND INSPECTIONS:

1. IMPACT WINDOWS AND DOORS HAVE BEEN INSTALLED.

CASE NO: CE16040790 1891 SW 29 AVE CASE ADDR:

UNITED PROPERTIES OF S FL LLC OWNER:

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INTERIOR RENOVATIONS.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. INSTALLED A SPLIT SYSTEM MECHANICAL AIR CONDITIONING SYSTEM.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16040945
CASE ADDR: 738 NW 15 WY
OWNER: SIP REALTY 1 LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. COMPLETE INTERIOR REMODEL.
- 2. RESTORED WALL FRAME AND INSTALLED DRYWALL.
- 3. CLOSED DOOR OPENINGS WITH WOOD FRAMING AND CMU UNITS.
- 5. REMODELED KITCHEN AND BATHS.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

- 1. ILLEGALLY INSTALLED NEW MECHANICAL CONDENSOR UNIT.
- 2. ILLEGALLY INSTALLED NEW MECHANICAL EVAPORATOR UNIT.
- 3. ILLEGALLY INSTALLED AIR CONDITIONING DUCT WORK.
- 4. WILL REQUIRE ALL BATHROOMS TO BE MECHANICALLY VENTED.

FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

- 1. ILLEGALLY INSTALLED NEW DOORS EXTERIOR AND INTERIOR.
- 2. ILLEGALLY INSTALLED NEW WINDOWS.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. ILLEGALLY INSTALLED NEW SINKS IN KITCHEN AND BATH.
- 2. ILLEGALLY INSTALLED NEW FAUCETS IN KITCHEN AND BATHS.
- 3. ILLEGALLY INSTALLED NEW WATER SPIGOTS.
- 4. ILLEGALLY INSTALLED NEW WATER LINES.
- 5. ILLEGALLY INSTALLED NEW WASTE LINES.
- 6. ILLEGALLY INSTALLED NEW WATER HEATER.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. ILLEGALLY INSTALLED NEW LIGHTING FIXTURES.
- 2. ILLEGALLY INSTALLED NEW SWITCHES AND OUTLETS.
- 3. ILLEGALLY INSTALLED NEW 220 OUTLETS FOR DRYER AND STOVE.
- 4. ILLEGALLY INSTALLED NEW ELECTRICAL WIRING FOR MECHANICAL SYSTEM.
- 5. ILLEGALLY INSTALLED WIRING.
- 6. ILLEGALLY LOW VOLATGE WIRING FOR MECHANICAL THERMOSTAT.

FBC(2014) 105.3.1.5

SUBMIT 2 SETS OF "AS BUILT" ARCHITECTURAL DRAWINGS/PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 116.2.1.3.1

WORK ILLEGALLY COMMENCED AND/OR ILLEGALLY COMPLETED PRIOR TO OBTAINING THE REQUIRED PERMITS IS DEEMED AS UNSAFE AND SUBJECT TO HAVE THE STRUCTURE BOARDED UP AND/OR DEMOLISHED UNDER THIS SECTION OF THE FLORIDA BUILDING CODE.

CASE NO: CE16050163 CASE ADDR: 1533 NW 19 AVE

OWNER: DRAGOSLAVIC, SLAVOLJUB & MARA

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. BUILT CARPORT.
- 2. BUILT FRONT PORCH.
- 3. BUILT ADDITION.
- 4. INSTALLED INTERIOR DROP CEILING.

FBC(2014) 105.3.1.4.10

THE FOLLOWING DESCRIBED WORK REQUIRES A ROOF PERMIT AND INSPECTIONS:

1. ILLEGALLY INSTALLED ARCHITECTURAL SHINGLE ROOF.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. ILLEGALLY INSTALLED A SPLIT AIR CONDITIONING SYSTEM.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

1. ILLEGALLY INSTALLED PLUMBING FIXTURES AND ALTERED THE PLUMBING SYSTEM SO THAT SEWAGE IS BACKING UP AT THE CLEANOUT BY THE SIDEWALK.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

1. INSTALLED ELECTRICAL FIXTURES AND WIRING ABOVE THE DROP CEILING.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

FBC(2014) 116.2.1.3.1

THIS BUILDING IN ITS PRESENT CONDITION DOES NOT
MEET THE CRITERIA OF THE FLORIDA BUILDING CODE FOR
MINIMUM MAINTENANCE STANDARD AND THE FORT
LAUDERDALE MINIMUM HOUSING CODE AND IT MUST BE
REPAIRED BY THE OWNERS OR DEMOLISHED:

1. DUE TO A FIRE THE STRUCTURE IS NOW DEEMED UNSAFE BY THE CITY.

CASE NO: CE16050226

CASE ADDR: 728 NW 6 AVE # A
OWNER: CASALE, ROSANNE D

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO: 1. FRAMED AND INSTALLED DRYWALL ON OFFICE

ENCLOSURE IN THIS WAREHOUSE.

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK DONE.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. INSTALLED SPLIT A/C MECHANICAL SYSTEM.
NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK DONE.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

1. INSTALLED NEW ELECTRICAL CIRCUITRY AND FIXTURES, INCLUDING LOW VOLTAGE CIRCUITS.

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK DONE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16050288
CASE ADDR: 304 SW 22 ST

OWNER: CONCESSION MANAGEMENT LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. ROOF STRUCTURAL REPAIRS.
- 2. DRYWALL REPAIRS IN THE KITCHEN.
- 3. WALL COVERING IN BATHTUB AREA REMOVED AND NEW TILEBACKER BEING INSTALLED.
- 4. SHED. (COMPLIED)

FBC(2014) 105.3.1.4.18

THE FOLLOWING DESCRIBED WORK REQUIRES A FENCE PERMIT AND INSPECTIONS:

1. NO PERMIT FOR FENCE IN PERMIT HISTORY. (COMPLIED)

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF NEW PLUMBING FIXTURES IN BATHROOM AND KITCHENS.
- 2. WATER HEATER.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF NEW ELECTRICAL FIXTURES, SWITCHES AND OUTLETS.
- 2. NOT LIMITED TO REWIRING AND BREAKER PANEL CHANGEOUT AND ALTERATIONS.

FBC(2014) 105.3.1.5

SUBMIT TWO SETS OF DRAWINGS/PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR.

MODIFICATIONS MADE PRIOR TO OBTAINING THE REQUIRED PERMITS MAY BE REQUIRED TO BE UNCOVERED FOR INSPECTIONS AND/OR CERTIFIED BY A LICENSED DESIGN PROFESSIONAL SOLELY AT THE DISCRETION OF THE BUILDING OFFICIAL. THIS INCLUDES BUT IT IS NOT LIMITED TO, ALL WALL STRUCTURES, ROOF STRUCTURES, ELECTRICAL SYSTEM, PLUMBING SYSTEM AND MECHANICAL SYSTEMS.

FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE HEREBY RESERVE THE AUTHORITY TO SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16050504
CASE ADDR: 1537 NW 19 AV
OWNER: LUMAX USA LLC
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. BUILT ROOF CANOPY ON RIGHT ELEVATION OF DWELLING. CANOPY IS STRUCTURALLY ATTACHED TO 1X6 FASCIA BOARD. (COMPLIED)

FBC(2014) 105.3.1.4.10

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. INSTALLED SPLIT MECHANICAL AIR CONDITIONING SYSTEM.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE16050712 CASE ADDR: 2308 NW 6 CT

OWNER: SANTORSOLVA, VITO MICHELE

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED HURRICANE SHUTTERS ON EXTERIOR WALL

OPENINGS.

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN PROGRESS OR WORK COMPLETED.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. INSTALLATION OF SPLIT A/C MECHANICAL SYSTEM.

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN PROGRESS OR WORK COMPLETED.

FBC(2014) 105.3.1.4.18

THE FOLLOWING DESCRIBED WORK REQUIRES A FENCE PERMIT AND INSPECTIONS:

1. INSTALLATION OF CHAIN LINK FENCE.
NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK IN PROGRESS OR WORK COMPLETED.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16050853
CASE ADDR: 1301 NW 18 CT
OWNER: 2771 LLC
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THE ROOF ON THIS RESIDENCE WAS REPLACED WITHOUT

PERMIT BETWEEN 2012 AND 2013.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16050861 CASE ADDR: 2780 NW 24 CT

OWNER: 2771 LLC INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. FRONT ENTRANCE DOOR REPLACED.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. CENTRAL A/C REPLACED AND RELOCATED.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE16051917

CASE ADDR: 1600 POINSETTIA DR

OWNER: BFA FLORIDA LAND TR # 20 LBS2016 FA

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. STRUCTURAL MODIFICATIONS TO THE INTERIOR STRUCTURE OF THIS BUILDING.
- 2. MODIFYING THE ORIGINAL FLOOR PLAN OF THE INTERIOR OF THE DWELLING.
- 3. STORAGE SHED.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. MECHANICAL ALTERATIONS BEING DONE TO THE MECHANICAL SYSTEM AND DUCT WORK OF THE STRUCTURE.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

1. INSTALLATION AND REPLACEMENT WITH NEW PLUMBING FIXTURES.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION AND REPLACEMENT OF ELECTRICAL FIXTURES AND REWIRING.
- 2. BREAKER PANEL REPLACEMENT WITH NEW CIRCUITS.

FBC(2014) 105.3.1.5

SUBMIT TWO SETS OF DRAWINGS OR PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR. DOCUMENTS FROM DESIGN PROFESSIONAL REQUIRE ORIGINAL COPIES, SIGNED AND SEALED BY DESIGN PROFESSIONAL.

FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE WILL REQUIRE SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16060517
CASE ADDR: 1042 NW 8 AV
OWNER: CM3 HOMES LLC
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL

PERMIT AND INSPECTIONS:

1. NEW INSTALLATION OF 2 SPLIT CENTRAL A/C MECHANICAL SYSTEMS. COMPRESSOR FOR FRONT UNIT MANUFACTURED DATED MAY 2008. COMPRESSOR FOR REAR UNIT DATED JANUARY 2009.

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK DONE.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF KITCHEN AND VANITY SINKS
- 2. NEW KITCHEN CABINETS AND VANITY CABINET.
- NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK DONE.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

1. INSTALLATION OF RECEPTACLES ONE OVER THE KITCHEN SINK IS UNVERIFIED AS BEING IN GFI CIRCUIT. REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH 406.4 (D)(1) THRU (D)(6), 210.8(B)(5) SINKS AND 210.8(B)(6) INDOOR WET LOCATIONS.

NO PERMITS IN PERMIT HISTORY TO ADDRESS WORK DONE.

FBC(2014) 110.2

BUILDING OFFICIAL AND/OR REPRESENTATIVE MAY REQUIRE SITE INSPECTIONS PRIOR TO THE APPROVAL AND ISSUANCE OF ALL AND ANY PERMITS AND/OR DETERMINATION OF COMPLIANCE WITH THE FLORIDA BUILDING CODE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16061700 CASE ADDR: 1553 NW 15 AVE

OWNER: 2771 LLC INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2010) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. INTERIOR REMODELING INSTALLATION OF WALL COVER IN WET SHOWER AREAS.
- 2. KITCHEN REMODEL, PERMIT WAS VOIDED.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. REPLACEMENT OF SPLIT A/C MECHANICAL SYSTEM.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. REPLACEMENT OF PLUMBING FIXTURES, KITCHENS AND BATHROOMS.
- 2. REPLACED HOT WATER HEATER.
- 3. INSTALLATION OF WATER SUPPLY LINES IN LAUNDRY ROOM.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF BREAKER CIRCUIT PANEL.
- 2. INSTALLATION OF RECEPTACLES.

REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH 406.4 (D) (1) THRU (D) (6)

GFI REQUIRED AS PER NEC 108.8.

R314.3.1 WHEN ALTERATIONS, REPAIRS OR ADDITIONS REQUIRING A PERMIT OCCUR, THE INDIVIDUAL DWELLING UNIT SHALL BE EQUIPPED WITH SMOKE ALARMS LOCATED AS REQUIRED FOR NEW DWELLINGS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16062293 CASE ADDR: 1716 SW 11 ST

OWNER: CONCESSION MANAGEMENT LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. INTERIOR ALTERATIONS INCLUDING NEW WALL AND CEILING DRYWALL COVERING.
- 2. SHED IN THE BACKYARD.
- FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF SPLIT MECHANICAL A/C SYSTEM.
- 2. INSTALLATION OF DUCT WORK.

FBC(2014) 105.3.1.4.18

THE FOLLOWING DESCRIBED WORK REQUIRES A FENCE PERMIT AND INSPECTIONS:

1. INSTALLATION OF FENCE.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF PLUMBING FIXTURES IN THE KITCHEN AND BATHROOMS.
- 2. INSTALLATION OF WASTELINES AND PLUMBING LINES IN KITCHEN, BATHROOMS AND LAUNDRY ROOM.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF RECEPTACLES AND CIRCUITS IN THE KITCHEN.
- 2. INSTALLATION OF SUB-PANEL.

OUTLETS: REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH 406.4 (D)(1) THRU (D)(6)
GFI'S REQUIRED AS PER NEC 108.8
OUTLET SPACING AS REQUIRED UNDER NEC 210.52

FBC(2014) 105.3.1.4.8

THE FOLLOWING INSTALLATION REQUIRES A PERMIT:

1. INSTALLATION OF CANOPY AWNING IN BACKYARD.

FBC(2014) 110.6

BUILDING OFFICIAL AND/OR REPRESENTATIVE MAY

REOUIRE SITE INSPECTIONS PRIOR TO THE APPROVAL AND

ISSUANCE OF ALL AND ANY PERMITS AND/OR

DETERMINATION OF COMPLIANCE WITH THE FLORIDA

BUILDING CODE.

._____

CASE NO: CE16062301

CASE ADDR: 745 W EVANSTON CIR

OWNER: MENDOZA, MARIA TERESA H/E

GARCIA, CARLOS ALBERTO

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.3.1.4.10

THE FOLLOWING DESCRIBED WORK REQUIRES A ROOF

PERMIT AND INSPECTIONS:

1. REPLACEMENT OF FLAT ROOF.

FBC(2014) 105.3.1.4.18

THE FOLLOWING DESCRIBED WORK REQUIRES A FENCE

PERMIT AND INSPECTIONS:
1. INSTALLATION OF FENCE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16070025

CASE ADDR: 401 RIVIERA ISLE 503 OWNER: BROOKS, CHRISTOPHER

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH

INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS, DEMOLITION AND REMODELING WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS MADE WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATION MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE INCLUDING AN ELECTRICAL PANEL REPLACED WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16070135

CASE ADDR: 4040 GALT OCEAN DR # 1105

OWNER: TALERICO, FRANK

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING AND INSPECTION PROCESS.

FBC(2014) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF RESIDENTIAL CONDOMINIUM UNITS TO THAT OF A BUSINESS WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

THE CONDOMINIUM UNITS ARE BEING RENTED FOR SOCIAL EVENTS AND GATHERINGS. CHANGE TO BUSINESS USES ALLOWS OCCUPANCY OF UP TO 49 OCCUPANTS AS REGULATED BY THE GUIDELINES OF FLORIDA BUILDING CODE WHICHEVER IS LESS. OCCUPANCY OF 50 OR MORE REQUIRES CHANGE OF USE TO THAT OF ASSEMBLY AS REGULATED BY THE GUIDELINES OF FLORIDA BUILDING CODE WHICHEVER IS LESS.

CASE NO: CE16070373
CASE ADDR: 2610 SW 5 ST
OWNER: SRZMIAI LLC
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

INTERIOR REMODELING.
 STRUCTURAL ALTERATIONS.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:
PLUMBING ALTERATIONS INCLUDING BUT NOT LIMITED

1. INSTALLING, REMOVING AND REPLACING PLUMBING COMPONENTS THAT MAY INCLUDE PLUMBING FIXTURES SUCH AS VALVES, TOILETS, SINKS, DIVERTERS, SHOWER HEADS, WATER SPIGOTS, WATER LINES, WASTE DISPOSAL PIPES, WATER HEATERS, SOLAR PANELS, IRRIGATION SYSTEM, PUMPS AND OTHER PLUMBING COMPONENTS

CONNECTED THE PLUMBING SYSTEM.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS: ELECTRICAL ALTERATIONS INCLUDING BUT NOT LIMITED TO:

1. INSTALLING, REMOVING AND REPLACING ELECTRICAL COMPONENTS THAT MAY INCLUDE SWITCHES, OUTLETS, ELECTRICAL FIXTURES, BREAKER/PANEL BOXES, METER BASES, WIRES, REWIRING, ELECTRONIC MONITORING SYSTEMS, FIRE ALARMS, BURGLAR ALARMS AND OTHER ELECTRICAL COMPONENTS CONNECTED TO THE ELECTRICAL SYSTEM.

FBC(2014) 105.3.1.5

SUBMIT TWO SETS OF DRAWINGS OR PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR. DOCUMENTS FROM DESIGN PROFESSIONAL REQUIRE ORIGINAL COPIES, SIGNED AND SEALED BY DESIGN PROFESSIONAL.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REOUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16070941 CASE ADDR: 3648 SW 17 ST

OWNER: CONTRERAS, DELIO D

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. INSTALLED ROOF STRUCTURE AT FRONT ENTRY FABRICATED FROM HURRICANE SHUTTERS.
- 2. INSTALLED ROOF STRUCTURE IN BACK YARD FABRICATED FROM HURRICANE SHUTTERS.
- 3. FABRICATED LAUNDRY ROOM STRUCTURE IN BACK
- 4. INSTALLED PREFABRICATED SHED AT BACK YARD.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

1. INSTALLATION OF SPLIT MECHANICAL A/C SYSTEM.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF PLUMBING IN KITCHEN INCLUDING NEW SINK AND WASTE LINES.
- 2. LAUNDRY ROOM PLUMBING.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REOUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. INSTALLED ELECTRICAL IN LAUNDRY ROOM.
- 2. INSTALLATION OF ELECTRICAL CIRCUITS, OUTLETS AND FIXTURES IN LAUNDRY ROOM.

OUTLETS: REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH 406.4 (D) (1) THRU (D) (6) GFI'S REQUIRED AS PER NEC 108.8

OUTLET SPACING AS REQUIRED UNDER NEC 210.52

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

._____

CASE NO: CE16071180
CASE ADDR: 512 NW 15 TER
OWNER: PASCAL 2014 LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. THE INTERIOR FLOOR PLAN CONFIGURATION OF THIS SINGLE FAMILY HOME HAS BEEN ALTERED.
- 2. KITCHEN HAS BEEN REMODELED.
- 3. BATHROOM HAS BEEN REMODELED.
- 4. BATHROOM HAS BEEN ADDED.
- 5. FRONT PORCH HAS BEEN BUILT AND ENCLOSED.
- 6. SECOND ACCESSORY STRUCTURE HAS BEEN BUILT AT BACK OF PARCEL AND CONVERTED TO A SECOND OCCUPIED RESIDENCE.
- 7. UTILITY LAUNDRY CLOSET BUILT AT BACK OF PRIMARY STRUCTURE.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF SPLIT MECHANICAL A/C SYSTEM.
- 2. INSTALLATION OF DUCT WORK.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF PLUMBING FIXTURES IN KITCHENS AND BATHS.
- 2. INSTALLATION OF WATER SUPPLY AND WASTE LINES TO SERVICE BATHROOM ADDED, BATHROOM REMODEL LAUNDRY AND WATER HEATER.
- 3. INSTALLATION OF WATER HEATER.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF WIRING CIRCUITS TO SERVICE WATER HEATER, WASHER-DRYER, MECHANICAL SYSTEM, RECEPTACLES AND FIXTURES.
- 2. INSTALLATION OF RECEPTACLES.
- 3. INSTALLATION OF BREAKER PANEL.
 OUTLETS: REPLACEMENT OF RECEPTACLES SHALL COMPLY
 WITH 406.4 (D)(1) THRU (D)(6)
 GFI'S REQUIRED AS PER NEC 108.8
 OUTLET SPACING AS REQUIRED UNDER NEC 210.52

FBC(2014) 105.3.1.5

SUBMIT TWO SETS OF DRAWINGS OR PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR. DOCUMENTS FROM DESIGN PROFESSIONAL REQUIRE ORIGINAL COPIES, SIGNED AND SEALED BY DESIGN PROFESSIONAL.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC (2014) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF SINGLE FAMILY TO DUPLEX WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CASE NO: CE16071710
CASE ADDR: 1378 SW 26 AV
OWNER: COOPER, IVONNE
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. INSTALLED OUTLETS FOR KITCHEN AND BATH REMODEL.
- 2. INSTALLED 220V OUTLET FOR CLOTHES DRYER.
- 3. INSTALLED NEW CIRCUITS TO SERVICE TANKLESS WATER HEATER.
- 4. INSTALLED NEW CIRCUIT TO SERVICE MECHANICAL A/C SYSTEM.
- 6. NEW CIRCUITS TO SERVICE SHED.
- 7. NEW CIRCUITS FOR THE INSTALLATION OF AN OUTLET TO SERVICE A RV.

OUTLETS: REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH 406.4 (D)(1) THRU (D)(6).
GFIS REQUIRED AS PER NEC 108..8
OUTLET SPACING AS REQUIRED UNDER NEC 210.52.

R314.3.1 ALTERATIONS, REPAIRS AND ADDITIONS: WHEN ALTERATIONS, REPAIRS OR ADDITIONS REQUIRING A PERMIT OCCUR, THE INDIVIDUAL DWELLING UNIT SHALL BE EQUIPPED WITH SMOKE ALARMS LOCATED AS REQUIRED FOR NEW DWELLINGS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

NEC 110.26

THE FOLLOWING ELECTRICAL LIFE AND SAFETY HAZARDS MUST BE CORRECTED IMMEDIATELY:

1. REFRIGIRATOR BLOCKING BREAKER PANEL ACCESS.

FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. EXTERIOR DOORS HAVE BEEN INSTALLED.
- 2. STORM SHUTTERS HAVE BEEN INSTALLED.
- 3. BATHROOM HAS BEEN REMODELED.
- 4. KITCHEN HAS BEEN REMODELED.
- 5. CONCRETE DRIVEWAY HAS BEEN CONSTRUCTED.
- 6. SHED HAS BEEN BUILT AT BACK OF PARCEL.
- 7. ALTERED THE STRUCTURAL WALL ENVELOPE TO INSTALL A SWING DOOR AT REAR OF MAIN STRUCTURE.
- 8. INSTALLED FRENCH DOOR.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

- 1. CENTRAL SPLIT MECHANICAL A/C SYSTEM HAS BEEN INSTALLED IN MAIN STRUCTURE.
- 2. DUCT WORK HAS BEEN INSTALLED IN THE MAIN STRUCTURE.
- 3. CENTRAL SPLIT MECHANICAL A/C SYSTEM HAS BEEN INSTALLED IN SHED.

FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

- 1. REPLACED EXTERIOR DOORS.
- 2. INSTALLED EXTERIOR DOOR.

FBC(2014) 105.3.1.4.18

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

- 1. FENCE AT BACK OF STRUCTURE TO DIVIDE BACK YARD.
- 2. INSTALLED 3 GATES.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLED WATER SUPPLY AND WASTE LINES TO SERVICE BATHROOM AND KITCHEN FIXTURES.
- 2. INSTALLED WATER SUPPLY AND WASTE LINES TO SERVICE LAUNDRY AREA.
- 3. INSTALLED WATER SUPPLY AND WASTE LINES TO SERVICE RV AT BACK YARD.
- 4. REPLACED PLUMBING FIXTURES IN KITCHEN AND BATH.
- 5. INSTALLED WATER SUPPLY LINES TO SERVICE TANKLESS WATER HEATER.

CASE NO: CE16071899

CASE ADDR: 4040 GALT OCEAN DR

OWNER: OCEAN MANOR CONDO ASSOC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. BUILT A THIRD TIKI HUT WHEN ONLY 2 HAVE BEEN

PERMITTED.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

1. INSTALLED WASTE OR GREASE LINE THAT IS DISCHARGING DIRECTLY INTO FLOOR DRAIN. (UNFOUNDED)

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

1. NEW ELECTRICAL CIRCUITS AND RECEPTACLES.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 116.2.1.2.5

ELECTRICAL SYSTEM HAS BEEN MODIFIED WITHOUT PERMITS. (COMPLIED)

FBC(2014) 116.2.1.2.6

INSTALLED WASTE OR GREASE LINE THAT IS DISCHARGING DIRECTLY INTO FLOOR DRAIN. (UNFOUNDED)

CASE NO: CE16080765

CASE ADDR: 1641 RIVERLAND RD

OWNER: TROPICAL DEVELOPERS LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. ALTERED THE EXTERIOR WALL, REMOVED SLIDING GLASS DOOR, INSTALLING CMU TO ACCOMONDATE A WINDOW.
- 2. ALTERED INTERIOR CMU BEARING WALL.
- 3. KITCHEN AND BATHROOM REMODEL.
- 4. INSTALLED TILE IN BATHROOM WET AREA WITH UNKNOWN TILE BACKER.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF MECHANICAL SPLIT A/C SYSTEM WITH DUCT WORK.
- 2. INSTALLATION OF MECHANICAL EXHAUST DUCTS.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. REPLACEMENT OF PLUMBING FIXTURES.
- 2. ALTERATION OF WASTELINES.
- 3. ALTERATION OF WATER SUPPLY LINES.
- 4. INSTALLATION OF WATER HEATER.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF RECESSED LIGHTING
- 2. INSTALLATION OF WIRING CIRCUITS.
- 3. INSTALLATION OF RECEPTACLES AND ELECTRICAL FIXTURES.
- 4. INSTALLATION OF NEW METER BASE AND WEATHERHEAD.

OUTLETS: REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH 406.4 (D)(1) THRU (D)(6).

GFIS REQUIRED AS PER NEC 108.8.

OUTLET SPACING AS REQUIRED UNDER NEC 210.52.

R314.3.1 ALTERATIONS, REPAIRS AND ADDITIONS:

WHEN ALTERATIONS, REPAIRS OR ADDITIONS REQUIRING A PERMIT OCCUR, THE INDIVIDUAL DWELLING UNIT SHALL BE EQUIPPED WITH SMOKE ALARMS LOCATED AS REQUIRED FOR NEW DWELLINGS.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE16091949
CASE ADDR: 545 NE 13 AV
OWNER: KREMEN, RONEN
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

FBC(2014) 111.1.1

SINGLE FAMILY STRUCTURE BEING OCCUPIED WITHOUT OBTAINING THE REQUIRED CERTIFICATE OF OCCUPANCY IN VIOLATION OF THIS SECION OF THE FLORIDA BUILDING CODE.

.....

CASE NO: CE13091180
CASE ADDR: 833 NW 19 AV

OWNER: BROWN, J M & SILLIE MAE EST

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2010) 105.1

- 1. WINDOWS AND DOORS ARE BEING REPLACED.
- 2. A/C UNIT WAS REPLACED.
- 3. ELECTRICAL WORK DONE. DISCONNECTED BOX TO THE A/C.
- 4. PLUMBING WORK DONE. A DRAIN LINE WAS EXPOSED ON THE NORTH SIDE OF THE HOUSE DRAINING ONTO THE GROUND.

FBC(2010) 105.4.15

WINDOWS AND DOORS INSTALLED WITHOUT THE REQUIRED PERMIT OR INSPECTIONS.

FBC(2010) 105.4.4

PLUMBING INSTALLED AND EXPOSED ON NORTH SIDE OF HOUSE AND DRAINING ONTO THE GROUND WITHOUT THE REQUIRED PERMIT OR INSPECTIONS.

FBC(2010) 105.4.5

ELECTRICAL WORK INSTALLED, DISCONNECT TO A/C WITHOUT THE REQUIRED PERMIT OR INSPECTIONS.

CASE NO: CE14110327 CASE ADDR: 433 NE 14 AVE

OWNER: ALEXANDRA SANTIBANEZ IRREV TR SANTI

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH THE INTERIOR DEMOLITION AND REMODELING WITHOUT THE REQUIRED

PERMITS AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE

IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15030470
CASE ADDR: 201 NE 16 AV
OWNER: HINDS, KEVIN &

LAYNE, PAUL J

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH STRUCTURAL ALTERATIONS DONE WITHOUT THE REQUIRED STRUCTURAL PERMIT AND/OR INSPECTIONS. THIS WORK INCLUDES BUT IS NOT LIMITED TO:

- 1. SECOND BATHROOM INSTALLED.
- 2. ROOMS SUB-DIVIDED WITH INTERIOR WALLS TO CREATE NEW ROOMS.
- 3. WOOD DECK WITH A WOOD PRIVACY SCREEN.

FBC(2010) 105.4.15

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF NEW WINDOW AND DOORS WITHOUT THE REQUIRED PERMITS AND OR INSPECTIONS.

FBC(2010) 105.4.4

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF PLUMBING WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS WHICH INCLUDES BUT IS NOT LIMITED TO:

1. A SECOND BATHROOM INSTALLED WITH A SHOWER, TOILET AND SINK.

FBC(2010) 105.4.5

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF ELECTRICAL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS THAT INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL INSTALLED IN THE SECOND BATHROOM AND OTHER CREATED ROOMS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE AFTER THE FACT PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY UNDER F.B.C. 109.3.3

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15081042

CASE ADDR: 441 S FTL BEACH BLVD OWNER: SOPHIA ENTERPRISES INC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS COMMERCIAL BUILDING SPACE HAS BEEN ALTERED WITH STRUCTURAL ALTERATIONS WHICH INCLUDE BUT ARE NOT LIMITED TO:

- 1. THE COMPLETE BUILD-OUT OF A RESTAURANT.
- 2. NEW WINDOWS AND DOORS.
- 3. INTERIOR ALTERATIONS WITHOUT THE REQUIRED STRUCTURAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS COMMERCIAL BUILDING SPACE HAS BEEN ALTERED WITH MECHANICAL ALTERATIONS WHICH INCLUDE BUT ARE NOT LIMITED TO:

1. NEW A/C MECHANICAL UNITS AND DUCT WORK INSTALLED WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS COMMERCIAL BUILDING SPACE HAS BEEN ALTERED WITH PLUMBING ALTERATIONS WHICH INCLUDE BUT ARE NOT LIMITED TO:

1. PLUMBING FIXTURES INSTALLED WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS COMMERCIAL BUILDING SPACE HAS BEEN ALTERED WITH ELECTRICAL ALTERATIONS WHICH INCLUDE BUT ARE NOT LIMITED TO:

- 1. ALARM CONTROL PANEL.
- 2. LIGHTING.
- 3. ELECTRICAL CONDUIT, ELECTRICAL DISCONNECTS, LOW VOLTAGE INSTALLED WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

THIS CODE CASE AND THE WORK DONE IN THIS COMMERCIAL BUILDING SPACE WILL REQUIRE ARCHITECTURAL DRAWINGS PREPARED BY A DESIGN PROFESSIONAL TO INCLUDE ALL OF THE VIOLATIONS THAT NEED TO BE PROPERLY PERMITTED, CORRECTED AND INSPECTED AS REQUIRED BY THE FLORIDA BUILDING CODE.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15082281

CASE ADDR: 2400 E OAKLAND PARK BLVD

OWNER: SP4 INVESTMENTS LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY/COMMERCIAL SPACE HAS BEEN ALTERED TO INCLUDE BUT IS NOT LIMITED TO:

- 1. A ROOM CONVERTED INTO A SHOWER.
- 2. A ROOM ALTERED INTO A KITCHENETTE WITH A WASHER AND DRYER. THIS WORK INCLUDES FRAMING AND DRYWALL WORK DONE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY/COMMERCIAL SPACE HAS BEEN ALTERED TO INCLUDE BUT IS NOT LIMITED TO:

1. MECHANICAL WORK INSTALLED FOR THE INSTALLATION OF A DRYER WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY/COMMERCIAL SPACE HAS BEEN ALTERED TO INCLUDE BUT IS NOT LIMITED TO:

1. PLUMBING WORK INSTALLED TO INCLUDE A NEW SHOWER, A WASHER MACHINE, AND A TANKLESS WATER HEATER INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY/COMMERCIAL SPACE HAS BEEN ALTERED TO INCLUDE BUT IS NOT LIMITED TO:

1. ELECTRICAL WORK INSTALLED TO INCLUDE ELECTRICAL FOR A WASHER AND DRYER, ELECTRICAL SUB PANEL INSTALLED UNDER THE KITCHENETTE SINK FOR A TANKLESS WATER HEATER AND POSSIBLY OTHER APPLIANCES. THERE ARE MISCELLANEOUS ELECTRICAL REPAIRS OR ALTERATIONS THAT HAVE BEEN MADE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE SEVERITY AND COMPLEXITY OF THIS CODE CASE AND THE ALTERATIONS THAT HAVE BEEN MADE TO THIS COMMERCIAL SPACE, THIS CASE WILL REQUIRE DRAWINGS PREPARED BY A DESIGN PROFESSIONAL. THESE DRAWINGS NEED TO DOCUMENT THE VIOLATIONS THAT EXIST AND THE METHOD AND CORRECTIONS THAT NEED TO BE MADE TO CORRECT ALL OF THE VIOLATIONS THAT EXIST IN THIS COMMERCIAL SPACE.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15091319
CASE ADDR: 307 NE 23 AV

OWNER: WALTER A CROWELL TR

CROWELL, WALTER A TRSTEE

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. THE INSTALLATION OF AN OUTDOOR KITCHEN STRUCTURE BUILT WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE INSTALLATION OF A GAS LINE INSTALLED FOR AN OUTDOOR KITCHEN WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15092005

CASE ADDR: 1800 N ANDREWS AVE # 05K OWNER: A & H LUTHY REV LIV TR

LUTHY, PETER TRSTEE

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES

BUT IS NOT LIMITED:

1. THE COMPLETE DEMOLITION OF THE KITCHEN AND BATHROOM WITHOUT THE REQUIRED STRUCTURAL PERMIT AND OR INSPECTIONS.

THIS OIL THOU HOLLOW

FBC(2014) 105.3.1.4.4

THIS CONDO UNIT HAS HAD PLUMBING ALTERATIONS PERFORMED WHICH INCLUDE BUT IS NOT LIMITED TO:

1. REMOVAL OF PLUMBING FIXTURES IN THE KITCHEN AND BATHROOM WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS CONDO UNIT HAS HAD ELECTRICAL ALTERATIONS PERFORMED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE REMOVAL OF THE CIRCUITS IN THE ELECTRICAL PANEL AND THE REMOVAL OF ALL THE ELECTRICAL DEVICES THROUGHOUT THIS CONDO UNIT WITHOUT THE REQUIRED PERMITS AND OR INSPECTIONS.

FBC(2014) 109.3.3

THE CONDO UNIT WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15100439
CASE ADDR: 2000 NE 17 WY

OWNER: SCHRONEN, GARY & PEGGY H/E

HOWELL, J & C

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. A TIKI HUT BEING BUILT IN THE REAR OF THE PROPERTY WITHOUT THE REQUIRED PERMITS AND/OR

INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE

IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15100769

CASE ADDR: 1700 SE 15 ST # PH401

OWNER: FALLA, JUSTIN B INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES

BUT IS NOT LIMITED TO:

- 1. THE KITCHEN WAS COMPLETELY DEMOLISHED.
- 2. THE TWO BATHROOMS WERE COMPLETELY DEMOLISHED.
- 3. INTERIOR WALLS BEING REMOVED AND DRYWALL INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS CONDO UNIT HAD BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE REMOVAL OF THE PLUMBING FIXTURES IN THE KITCHEN AND BATHROOMS WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE REMOVAL OF THE ELECTRICAL DEVICES IN THE KITCHEN, BATHROOMS AND OTHER WALL AREAS WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC (2014) 107.1.1

THE CONDO UNIT OWNER WILL BE REQUIRED TO SUBMIT ARCHITECTURAL DRAWINGS TO ADDRESS ALL OF THE RENOVATION WORK BEING DONE IN THIS UNIT. A COMPLETE DEMOLITION DRAWING/PAGE WILL NEED TO BE INCLUDED AND ADDRESS THE INTERIOR WALLS THAT HAVE BEEN REMOVED AND THE FUTURE LAYOUT OF THE PROPOSED RENOVATION.

FBC(2014) 110.6

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE ATF PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15101220 CASE ADDR: 1230 NW 7 AV

OWNER: GALA INVESTMENTS GROUP LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. A COMPLETE INTERIOR REMODELING OF THE KITCHEN AND BATHROOM.
- 2. THERE IS A SECOND BATHROOM THAT WAS ILLEGALLY INSTALLED IN THIS HOUSE AND WAS NEVER PERMITTED. THIS WORK HAS BEEN PERFORMED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE MECHANICAL SYSTEM INCLUDING THE DUCT WORK BEING REMOVED AND REPLACED WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. THE PLUMBING BEING ALTERED IN THE KITCHEN AND BATHROOM.
- 2. A SECOND BATHROOM WAS ADDED WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. THE ELECTRICAL BEING ALTERED IN THE KITCHEN AND BATHROOM.
- 2. A SECOND BATHROOM ILLEGALLY ADDED WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

THIS PROPERTY AND CODE CASE WILL REQUIRE DRAWINGS PREPARED BY A DESIGN PROFESSIONAL TO ADDRESS AND PERMIT THE SECOND BATHROOM THAT WAS ILLEGALLY INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15101589

CASE ADDR: 3200 NE 36 ST # 411
OWNER: BAUCO, DOMENICO
BAUCO, MARISA

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.3.1.4.5

THIS CONDO UNIT HAS BEEN ALTERED WITH A KITCHEN AND BATHROOM REMODEL WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 110.2

A PRELIMINARY INSPECTION WILL BE REQUIRED BEFORE THE AFTER THE FACT PLAN REVIEW IS APPROVED.

FBC(2014) 110.6

THE CONDO UNIT OWNER WILL BE REQUIRED TO SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2014) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH A KITCHEN AND BATHROOM REMODEL WHICH INCLUDES BUT IS NOT LIMITED TO:

1. FRAMING AND DRYWALL WITHOUT THE REQUIRED STRUCTURAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 109.3.3

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

CASE NO: CE15101770

CASE ADDR: 3001 N OCEAN BLVD

OWNER: GUMMAKONDA PROPERTIES INC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. THE PROPERTY IS BEING USED AS A COMMERCIAL/PAY FOR PUBLIC PARKING LOT WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC (2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15101783

CASE ADDR: 1180 SEABREEZE BLVD

OWNER: SOUTHEAST HOSPITALITY CORP

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. CONCRETE RESTORATION WORK BEING PERFORMED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS ELECTRICAL VIOLATION WHICH INCLUDE BUT ARE NOT LIMITED TO:

1. VIOLATIONS THAT NEED TO BE CORRECTED AND WORK PERFORMED BY A LICENSED ELECTRICIAN WITH THE REQUIRED ELECTRICAL PERMIT AND INSPECTIONS.

FBC(2014) 107.1.1

THIS PROPERTY AND THE CONCRETE RESTORATION WORK THAT IS BEING PERFORMED WILL REQUIRE ARCHITECTURAL PLANS PREPARED BY A DESIGN PROFESSIONAL THAT WILL OUTLINE THE SCOPE OF WORK AND THE NEEDED REPAIRS THAT NEED TO BE MADE. THE WORK WILL REQUIRE PERMITS OBTAINED BY A GENERAL CONTRACTOR AND A STRUCTURAL ENGINEER WILL NEED TO BE THE SPECIAL INSPECTOR OF RECORD AND RECORDED THROUGH THE PERMITTING PROCESS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE ATF PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15102509

CASE ADDR: 2500 E COMMERCIAL BLVD

OWNER: ALTO PROPERTY MANAGEMENT LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THIS COMMERCIAL OFFICE SPACE AND THE ADJOINING UNITS, PROFESSIONAL DRAWINGS PREPARED BY A DESIGN PROFESSIONAL WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED AND BROUGHT INTO COMPLIANCE PER FLORIDA BUILDING CODE.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2014) 105.1

THIS COMMERCIAL SPACE HAS BEEN COMPLETELY
REMODELED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. FRAMING AND DRYWALL INSTALLED WITHOUT THE
REQUIRED STRUCTURAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS COMMERCIAL SPACE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING FIXTURES INSTALLED WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS COMMERCIAL SPACE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL WIRING AND DEVICES INSTALLED WITHOUT THE REQUIRED ELECTRICAL PERMITS AND/OR INSPECTIONS.

CASE NO: CE15110968

CASE ADDR: 3821 N OCEAN BLVD OWNER: MY FL 3821 LLC INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. INTERIOR ROOM REMODELING INCLUDING FRAMING, DRYWALL, INTERIOR WALL BOARD CLADDING, WOOD PLATFORM DECK INSTALLED WITHOUT THE REQUIRED STRUCTURAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL DEVICES BEING REMOVED AND REPLACED, ELECTRICAL WIRING BEING INSTALLED OR ALTERED TO ACCOMMODATE NEW ELECTRICAL FIXTURES AND LOW VOLTAGE LIGHTING INSTALLED WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. THE PLUMBING FIXTURES ARE BEING REMOVED AND REPLACED.
- 2. THERE ARE ROOMS WHERE A KITCHENETTE WAS REMOVED, A WOOD PLATFORM DECK BUILT AND JACUZZI TUBS INSTALLED. THIS WORK HAS BEEN PERFORMED WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE SCOPE OF WORK, THE DOLLAR AMOUNT OF THE IMPROVEMENTS BEING MADE, THE POTENTIAL LIABILITY TO THIS HOTEL BUILDING AND OCCUPANTS, PROFESSIONAL DRAWINGS PREPARED BY A DESIGN PROFESSIONAL WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED AND BROUGHT INTO COMPLIANCE PER THE FLORIDA BUILDING CODE.

FBC (2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE14070534

CASE ADDR: 200 S BIRCH RD # 814 OWNER: SCHILLIZZI, LANCE

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2010) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH AN INTERIOR RENOVATION WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 110.9

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW

AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS

CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15120410 CASE ADDR: 824 NE 20 AV

OWNER: HG MIDDLE RIVER INVESTMENTS LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS RENOVATIONS, PAVERS AND FENCE INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS AND MINI SPLIT A/C SYSTEMS INSTALLED WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15120949
CASE ADDR: 1122 NE 1 AV
OWNER: H.O.M.E.S INC
INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE WITH A KITCHEN AND BATHROOM REMODEL INCLUDING REMOVING AND REPLACING THE TILE BACKING BOARD AND INSTALLING A FRENCH DOOR UNIT WITHOUT THE REQUIRED PERMITS AND OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE TO THE KITCHEN AND BATHROOM, REMOVING AND REPLACING THE PLUMBING FIXTURES AND INSTALLING A TANKLESS WATER HEATER WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE TO THE KITCHEN AND BATHROOM REMOVING AND REPLACING ELECTRICAL DEVICES WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16010199

CASE ADDR: 2811 NE 56 CT

OWNER: LACHO & FRANZ LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. ALTERING THE SEAWALL CAP.
- 2. ALTERING EXTERIOR OPENINGS ON THE HOUSE.
- 3. PATIO ENCLOSURE.
- 4. INTERIOR RENOVATIONS WITHOUT THE REQUIRED STRUCTURAL PERMIT AND/OR INSPECTIONS.

FBC (2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. REMOVING AND REPLACING THE MECHANICAL SYSTEM WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. REMOVING AND REPLACING PLUMBING FIXTURES WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. REMOVING AND REPLACING ELECTRICAL WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY, SEVERITY, LIFE SAFETY, AND POTENTIAL LIABILITY OF THE VIOLATIONS FOR THIS PROPERTY, PROFESSIONAL DRAWINGS PREPARED BY A DESIGN PROFESSIONAL WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED AND BROUGHT INTO COMPLIANCE PER FLORIDA BUILDING CODE.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY.

CASE NO: CE16011026
CASE ADDR: 1009 NE 17 CT
OWNER: CONROY, KYLE
INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS FRAMING AND DRYWALL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS. THIS PROPERTY WAS ORIGINALLY PERMITTED AS A TWO FAMILY DWELLING AND WAS ILLEGALLY CONVERTED IN A TRIPLEX UNIT WITHOUT THE PROPERTY CERTIFICATE OF OCCUPANCY. THERE HAS BEEN EXTENSIVE REMODELING WORK DONE ON THIS BUILDING WHICH INCLUDES BUT IS NOT LIMITED TO WINDOWS AND DOORS REPLACED, KITCHEN AND BATHROOM REMODELED, LAYOUT OF THE BUILDING HAS BEEN ALTERED.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATION MADE:
REMODELING KITCHENS, BATHROOMS, REMOVING AND
REPLACING PLUMBING FIXTURES WITHOUT THE REQUIRED
PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE:
ELECTRICAL PANELS REPLACED, DISCONNECTS
INSTALLED, ELECTRICAL OUTLETS, SWITCHES, DEVICES
REMOVED, REPLACED OR RELOCATED WITHOUT THE
REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS MADE WITH REMOVING AND REPLACING THE A/C UNITS WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY, PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

CASE NO: CE16011103

CASE ADDR: 2624 NE 30 PL # 103B OWNER: WILLIAMS, ASHLEY DAWN

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. RENOVATIONS AND WORK BEING DONE SUCH AS FRAMING AND DRYWALL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS CONDO BUILDING/UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. HAVING MECHANICAL ALTERATIONS MADE WHERE A/C UNITS HAVE BEEN INSTALLED WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL INSTALLED AND/OR ALTERED WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16021331

CASE ADDR: 1881 MIDDLE RIVER DR # 502
OWNER: LEVEQUE, GAYLE LEVEQUE, PATRICK

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE COMPLETE REMODEL OF THE KITCHEN, BATHROOMS WITH ALTERATIONS MADE SUCH AS FRAMING, DRYWALL, WINDOWS REPLACED, DROPPED CEILING IN KITCHEN WITH ELECTRICAL AND COMPROMISED THE FIREWALL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE MECHANICAL EXHAUST FANS BEING REMOVED, REPLACED OR RELOCATED WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE KITCHEN AND BATHROOMS BEING REMODELED WITH PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE KITCHEN AND BATHROOMS BEING REMODELED WITH ROMEX WIRING, BLUE CUT IN BOXES, THE KITCHEN LAYOUT HAS BEEN ALTERED AND NOW THE REFRIGERATOR IS BLOCKING THE ELECTRICAL PANEL AND OTHER ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING CONDO UNITS AND COMMUNITY, PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 109.3.3

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16021507
CASE ADDR: 215 NE 16 AVE

OWNER: VICTORIA PALMS CONDO ASSN INC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. THE INSTALLATION OF A FENCE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16050534 CASE ADDR: 2900 NE 30 ST

OWNER: LAUDERDALE TOWER CONDO ASSN INC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE REQUIRED WORK TO BE DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE

VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F./CODE CASE PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2014) 116.2.1.2.2

THE BUILDING HAS AREAS WHERE THERE IS CONCRETE DETERIORATION WHICH INCLUDES BUT IS NOT LIMITED TO BALCONY RAILINGS FAILING WHICH HAS CREATED AN UNSAFE CONDITION FOR THE BUILDING AND POSES POTENTIAL LIFE SAFETY ISSUES FOR THE OCCUPANTS OF THIS BUILDING.

CASE NO: CE16050574

CASE ADDR: 2500 NE 48 LA # 509 OWNER: KEBE, STANLEY W INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES

BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS FRAMING, DRYWALL, REMODELING THE KITCHEN AND TWO BATHROOMS WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 109.3.3

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16060234

CASE ADDR: 2715 N OCEAN BLVD # PHB OWNER: BOYACIOGLU, GARABAT

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS FRAMING AND DRYWALL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS MADE WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATION MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. UNDER SECTION 9-47 FOUR TIMES THE PERMIT FEES MAY APPLY.

FBC (2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16061714

CASE ADDR: 1400 NE 56 ST # 209
OWNER: DIXIE REALTY LLC
INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE TO THE KITCHEN AND BATHROOM BEING FULLY REMODELED INCLUDING FRAMING AND DRYWALL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE TO THE KITCHEN AND BATHROOM WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE TO THE KITCHEN AND BATHROOM WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2014) 109.3.3

THE PROPERTY/CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

CASE NO: CE16070628

CASE ADDR: 2701 N OCEAN BLVD OWNER: EMBASSY TOWER INC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY/CONDO HAS BEEN ALTERED WHICH

INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS FRAMING AND DRYWALL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY/CONDO HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. MECHANICAL ALTERATIONS MADE WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY/CONDO HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATION MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY/CONDO HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC (2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT AT A MINIMUM WILL APPLY AND BASED ON THE CIRCUMSTANCES AND SEVERITY OF THE VIOLATIONS AND CITY RESOURCES INVOLVED THIS CASE MAY BE SUBJECT TO FOUR TIMES THE FEE UNDER SECTION 9-47. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16080753

CASE ADDR: 14 ISLA BAHIA DR OWNER: GROSVENOR, JUDSON

J MARK GROSVENOR TR ETAL

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. EXTENSIVE ALTERATIONS MADE SUCH AS STEEL BEAMS INSTALLED, FRAMING, DRYWALL, A FULL INTERIOR RENOVATION WITHOUT THE REQUIRED PERMITS AND/OR

INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. EXTENSIVE MECHANICAL ALTERATIONS MADE WITHOUT THE REQUIRED MECHANICAL PERMITS AND\OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. EXTENSIVE PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. EXTENSIVE ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES, PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT AT A MINIMUM WILL APPLY. BECAUSE OF THE SEVERITY OF THE SCOPE OF WORK, THE DOLLAR AMOUNT OF THE IMPROVEMENTS BEING MADE AND THE BLATANT ATTEMPT TO CIRCUMVENT THE REQUIREMENTS OF THE FLORIDA BUILDING CODE AND THE CITY OF FORT LAUDERDALE BUILDING DEPARTMENT THIS CODE CASE IS SUBJECT TO FOUR TIMES THE FEE ON ALL REQUIRED AFTER THE FACT PERMITS THAT WILL BE REQUIRED FOR COMPLIANCE FOR THIS CODE CASE.

FBC (2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16080885

CASE ADDR: 86 ISLE OF VENICE # 3

OWNER: 86 ISLE OF VENICE INC TR 86 ISLE

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. INTERIOR ALTERATIONS MADE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.
- 2. THE WORK THAT HAS BEEN PERFORMED HAS CREATED A POTENTIAL LIFE SAFETY ISSUE.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC (2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16090447

CASE ADDR: 100 N FEDERAL HWY # CU-1

OWNER: WAVERLY 1 & 2 LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. INTERIOR REMODEL/BUILD OUT ALTERATION OF THIS OFFICE SPACE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16090595 CASE ADDR: 3134 NE 9 ST

OWNER: CHIEFTAIN HOLDINGS LP

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS INTERIOR DEMOLITION AND INTERIOR REMODELING INVOLVING STRUCTURAL, ELECTRICAL, MECHANICAL AND PLUMBING PERFORMED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC (2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16091338

CASE ADDR: 2841 N OCEAN BLVD # 907

OWNER: LLEWELLYN, JUDY C

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ALTERATIONS MADE SUCH AS A FULL BATHROOM DEMOLITION/REMODEL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING ALTERATIONS MADE WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS PROPERTY/CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL ALTERATIONS MADE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY OF THE UNPERMITTED WORK BEING DONE, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THE SURROUNDING PROPERTIES AND COMMUNITY PROFESSIONAL DRAWINGS PREPARED BY AN ARCHITECT OR ENGINEER WILL BE REQUIRED TO ADDRESS EACH VIOLATION AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 109.3.3

THE PROPERTY/CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. BASED ON THE CIRCUMSTANCE OF THIS CODE CASE THIS CASE IS SUBJECT TO FOUR TIMES THE PERMIT FEES UNDER SECTION 9-47.

FBC (2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE16031538

CASE ADDR: 1413 NW 1 AV

OWNER: ALEXANDRE, TONY

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

- 1. KITCHEN AND BATHROOM RENOVATIONS.
- 2. ADDITION OF LIGHT FIXTURES.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

.....

CASE NO: CE14090494

CASE ADDR: 1205 NE 3 AV

OWNER: BLAKE, HEATHER

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC (2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:
1. BATHROOM REMODEL.

CASE NO: CE15050755

CASE ADDR: 1200 NW 9 ST

OWNER: ASSIS HOMES LLC

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. SINGLE FAMILY RESIDENCE CONVERTED INTO A DUPLEX.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE15061198

CASE ADDR: 1616 SE 2 CT

OWNER: FINN, ZACHARY

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. PAVERS INSTALLED ON DRIVEWAY AND SWALE AREA.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITING PROCESS.

CASE NO: CE15080754
CASE ADDR: 1706 NW 14 CT
OWNER: TUCHOW, TYLER
INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. GARAGE WAS CONVERTED INTO LIVING SPACE.

CONSTRUCTION OF A SECOND BATHROOM.
 AIR CONDITIONING SYSTEM CHANGE OUT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITING PROCESS.

CASE NO: CE15111675

CASE ADDR: 39 CASTLE HARBOR ISLE

OWNER: LECLAIR, DANIEL INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. BOAT LIFT INSTALLATION.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16051188
CASE ADDR: 1201 NW 16 CT

OWNER: CHEVEULON, NERUBIN H/E

CHEVEULON, LEDILE

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. WOOD FENCE REPLACEMENT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITING PROCESS.

CASE NO: CE16062033 CASE ADDR: 3130 NW 69 CT

OWNER: REYNA, KATHERINE M INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. CENTRAL AIR CONDITIONER REPLACEMENT.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16062148

CASE ADDR: 1431 SW 32 CT

OWNER: SPAAPEN, JULES

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. CARPORT CONVERTED INTO LIVING AREA.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE16070893 CASE ADDR: 2139 SW 1 CT

OWNER: UNITED LEGAL SERVICES LLC TRSTEE

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. WOOD FENCE BUILT ON THE FRONT OF THE PROPERTY.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE15111269
CASE ADDR: 1117 NW 4 AVE
OWNER: MAYNARD, JUNIOR
INSPECTOR: FRANK ARRIGONI

VIOLATIONS: FBC (2014) 105.1

DURING AN ONSITE INSPECTION OF THIS PROPERTY FOR A REQUEST TO VOID A EXPIRED FENCE PERMIT I NOTICED WORK HAD BEEN DONE:

- 1. WINDOW AND DOOR REPLACEMENT.
- 2. KITCHEN AND BATH PLUMBING FIXTURE REPLACEMENT.
- 3. ELECTRICAL SERVICE UPGRADE.
- 4. PLUMBING PIPE TIED INTO CLEAN OUT CAP.
- 5. IT APPEARS THE FLAT ROOF HAS BEEN REROOFED.
- 6. THERE IS A WOOD FENCE THAT WAS NOT PERMITED.

12/23/15 A REVIEW OF THE ORIGINAL PLAN AND THE ATF PLAN SUBMITTED SHOWS:

- 1. THE LAUNDRY WAS A CLOSET AND THE PORCH HAS BEEN CONVERTED TO A BEDROOM.
- 2. THE FRONT ENTRANCE HAS BEEN RELOCATED. THIS CAN BE SEEN IN PHOTOS ON BCPA WEB SITE.
- 3. THE A/C SYSTEM HAS BEEN ALTERED DUCT WORK HAS BEEN ADDED TO THE BEDROOM ADDITION.
- 4. THE A/C AIR HANDLER AND CONDENSING UNITS REPLACED.

CASE NO: CE16032002 CASE ADDR: 2349 SW 34 TER

OWNER: UNITED PROPERTIES OF S FL LLC

INSPECTOR: FRANK ARRIGONI

VIOLATIONS: FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

- 1. NEW INSTALLATION OF MECHANICAL AC SYSTEM.
- 2. INSTALLATION OF DUCT WORK.
- 3. INSTALLATION OF EXHAUST FANS IN BATH AREAS.

FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. THE EXISTING WALL AND CEILING COVERING WAS REMOVED FROM THE INTERIOR OF THE KITCHEN, BATHROOMS, DINING AREA AND LIVING AREA.
- 2. THE CARPORT HAS BEEN CONVERTED TO LIVING SPACE.
- 3. THE FRONT PORCH HAS BEEN EXTENDED AT THE ENTRANCE.
- 4. STRUCTURAL BLOCK WALL CONSTRUCTED WITH NO TIE BEAM OR BOND BEAM REQUIRING ENGINEERING.
- 5. INSTALLATION OF SOLAR PANEL ON EXTERIOR OF STRUCTURE.
- 6. WALL COVERING FOR TILED WET AREAS IN BATHROOM AND KITCHENS.
- 7. INTERIOR PARTITIONS CONSTRUCTED.
- 8. SOFFIT CONSTRUCTED FOR NEW DUCTWORK.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. INSTALLATION OF WATER HEATER.
- 2. REMOVAL AND INSTALLATION NEW PLUMBING FIXTURES IN KITCHEN AND BATHROOMS INCLUDING BUT NOT LIMITED TO SINKS, FAUCETS, TOILETS, BATHTUBS.
- 3. PLUMBING WASTE LINES.
- 4. WATER SUPPLY LINES.
- 5. 3 INCH SANITARY LINE RUN BELOW THE SLAB FROM BATH TO THE UNPERMITTED CARPORT ENCLOSURE.
- 6. WATER HEATER.
- 7. SUPPLY AND RETURN LINES FOR SOLAR PANELS.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. NEW ELECTRICAL SERVICE.
- 2. REWIRING AND INSTALLATION OF NEW CIRCUITS THROUGHOUT THE ENTIRE STRUCTURE.
- 2. WEATHERHEAD UNDER ROOF SOFFIT NOT PER NEC230.24.
- 3. WIRING FOR NEW ELECTRICAL FIXTURE INSTALLATIONS.
- 4. WIRING OF INSTALLATION OF NEW SWITCHES.
- 5. WIRING FOR NEW RECEPTACLE INSTALLATIONS.
- 6. WIRING FOR NEW WATER HEATER.
- 7. BREAKER PANEL INSTALLATION WITH ALL WIRING CIRCUITS.
- 8. RECESSED LIGHT INSTALLATION.

OUTLETS: REPLACEMENT OF RECEPTACLES SHALL COMPLY WITH 406.4 (D) (1) THRU (D) (6) GFI'S REQUIRED AS PER NEC 108.8 OUTLET SPACING AS REQUIRED UNDER NEC 210.52 R314.3.1 ALTERATIONS, REPAIRS AND ADDITIONS: WHEN ALTERATIONS, REPAIRS OR ADDITIONS REQUIRING A PERMIT OCCUR, THE INDIVIDUAL DWELLING UNIT SHALL BE EQUIPPED WITH SMOKE ALARMS LOCATED AS REQUIRED FOR NEW DWELLINGS.

FBC(2014) 105.3.1.5

SUBMIT TWO SETS OF DRAWINGS OR PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPES OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR. DOCUMENTS FROM DESIGN PROFESSIONAL REQUIRE ORIGINAL COPIES, SIGNED AND SEALED BY DESIGN PROFESSIONAL.

FBC (2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 115.1

A STOP WORK WAS ISSUED.

STOP WORK ORDER ISSUED SINCE WORK IS ONGOING WITHOUT THE REQUIRED PERMITS. VIOLATION OF STOP WORK ORDER IS SUBJECT TO THE MAXIMUM PENALTIES AS OUTLINED UNDER THIS SECTION OF THE FLORIDA BUILDING CODE.

CASE NO: CE16040644

CASE ADDR: 325 ISLE OF CAPRI

OWNER: GALLUZZO, GEORGE R JR & MELISSA

INSPECTOR: FRANK ARRIGONI

VIOLATIONS: FBC (2014) 105.1

THE PROPERTY HAS BEEN ALTERED IN THE FOLLOWING

MANNER:

1. THE DOCK HAS BEEN REPLACED ON THE EXISTING PILING AND STAIRS ADDED TO THE SOUTH END.

FBC(2014) 105.3.1.4.4

1. WATER LINES INSTALLED ON DOCK

FBC(2014) 105.3.1.4.5

1. ELECTRICAL SERVICE ADDED TO DOCK

FBC(2014) 110.6

THE REQUIRED INSPECTIONS FOR THIS WORK WERE NOT

DONE.

CASE NO: CE16072241
CASE ADDR: 3110 SW 21 ST
OWNER: MAHMOOD, UNEEZA
RASHID, MAHOOD

INSPECTOR: MARIO CARRASQUEL

VIOLATIONS: FBC (2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN

THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. ROOF STRUCTURE REPAIRS REQUIRES ENGINEERING DRAWINGS.
- 2. NEW DRYWALL COVERINGS ON WALLS.
- 3. NEW DRYWALL ON CEILINGS.
- 4. REMODEL KITCHEN AND BATHROOMS.
- 5. COVERED OPENINGS FROM WALL A/C UNITS IN EXTERIOR WALLS.
- 6. ROOF STRUCTURE AT BACK ELEVATION OF CORRUGATED MATERIAL.

FBC(2014) 105.3.1.4.11

THE FOLLOWING DESCRIBED WORK REQUIRES A MECHANICAL PERMIT AND INSPECTIONS:

- 1. INSTALLATION FOR MECHANICAL A/C EQUIPMENT.
- 2. INSTALLATION OF MECHANICAL DUCT WORK.

FBC(2014) 105.3.1.4.15

THE FOLLOWING DESCRIBED WORK REQUIRES A DOOR AND WINDOW PERMIT AND INSPECTIONS:

1. REPLACING DOORS AND WINDOWS.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. NEW WATER SUPPLY LINES.
- 2. NEW WASTE LINES.
- 3. NEW BATHROOM AND KITCHEN FIXTURES.

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. ISTALLING NEW WIRING CIRCUITS.
- 2. INSTALLING NEW RECEPTACLES.
- 3. INSTALLING NEW ELECTRICAL FIXTURES.
- 4.INSTALLING NEW WIRING CIRCUITS FOR MECHANICAL EQUIPMENT.
- 5. INSTALLING NEW BREAKER PANEL.

FBC(2014) 105.3.1.5

SUBMIT TWO SETS OF DRAWINGS OR PLANS FROM A QUALIFIED LICENSED DESIGN PROFESSIONAL ADDRESSING ALL THE SCOPE OF WORK FOR ALL STRUCTURAL MODIFICATIONS AND ALTERATIONS TO THE BUILDING STRUCTURE AND BUILDING SYSTEMS, EXTERIOR AND INTERIOR. DOCUMENTS FROM DESIGN PROFESSIONAL REQUIRE ORIGINAL COPIES, SIGNED AND SEALED BY DESIGN PROFESSIONAL.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

HEARING TO IMPOSE FINES

CHAPTER 11, FORT LAUDERDALE, CODE OF ORDINANCE

CASE NO: CE07101439
CASE ADDR: 1518 DAVIE BLVD

OWNER: FEDERAL HOME LOAN MORTGAGE CORP

INSPECTOR: JORG HRUSCHKA, TRANSFERRED

VIOLATIONS: 9-280(B)

BUILDING IS NOT STRUCTURALLY SOUND AND MAINTAINED IN A SECURE AND ATTRACTIVE MANNER.

9-280(D)

THE EXTERIOR WALLS ARE SUBJECT TO DETERIORATION AND ARE NOT PROTECTED FROM THE ELEMENTS. PAINT IS PEELING, CRACKING AND FADING. CAULKING IS MISSING. STRUCTURAL CRACKS ALLOW WATER PENETRATION.

9-280(H)

THE FENCE IS IN DISREPAIR.

FBC 105.1

- 1) NEW WINDOWS WERE INSTALLED.
- 2) THE MAIN KITCHEN WAS REMODELED.
- 3) A SHED WAS INSTALLED, AND IS BEING USED AS AN UTILITY/LAUNDRY ROOM.
- 4) THE ENCLOSED CARPORT WAS CONVERTED INTO AN APARTMENT.
- 5) A SECOND KITCHEN WAS INSTALLED IN THE CARPORT CONVERSION
- 6) THE PORCH WAS ENCLOSED.
- 7) EXTERIOR DOORS WERE INSTALLED/REPLACED.
- 8) A BATHROOM WAS ADDED.
- 9) INTERIOR WALLS WERE CONSTRUCTED TO CREATE ADDITIONAL BEDROOMS.

FBC 105.2.11

- 1) WALL AND WINDOW A/C UNITS WERE INSTALLED
- 2) A DRYER WAS INSTALLED IN SHED-HOUSE, WITHOUT PROPER VENTILATION.

FBC 105.2.4

- 1) BATHROOM SINKS AND TOILETS WERE REPLACED.
- 2) KITCHEN SINKS WERE REPLACED, AND A DISPOSAL WAS ADDED.
- 3) GENERAL ALTERATIONS TO THE PLUMBING SYSTEMS WERE DONE.
- 4) A WASHER & DRYER WAS INSTALLED IN AN EXTERIOR SHED.
- 5) A KITCHEN SINK WAS INSTALLED IN THE CARPORT CONVERSION, A WATER HEATER AS RELOCATED TO THE UTILITY SHED.

FBC 105.2.5

- 1) EXTERIOR AND INTERIOR OUTLETS WERE MOVED AND ADDED.
- 2) CIRCUITS FOR CARPORT AREA WERE ADDED.
- 3) CIRCUITS FOR ILLEGAL KITCHEN WERE ADDED.
- 4) INTERIOR BREAKER PANEL WAS REPLACED, AN EXTERIOR PANEL WAS ADDED INSIDE THE SHED TO POWER THE WASHER & DRYER.
- 5) GENERAL PREMISE WIRING WAS ALTERED.
- 6) THE ELECTRICAL LOADS IMPOSED ON THE CIRCUITS INCLUDING BUT NOT LIMITED TO THE PORCH BEDROOM, LIVING ROOM AND CARPORT, EXCEED THE CAPACITY OF THE EXISTING CIRCUITRY.

FBC 109.6

WORK WAS PERFORMED AND COVERED WITHOUT OBTAINING THE REQUIRED APPROVALS.

FBC 110.1.1

THE SINGLE FAMILY RESIDENCE WAS CONVERTED INTO A DUPLEX WITHOUT OBTAINING A CERTIFICATE OF OCCUPANCY.

FBC 1604.1

THE ENCLOSURES WERE NOT CONSTRUCTED IN ACCORDANCE WITH STRENGTH REQUIREMENTS FOR THE LOADS IMPOSED.

FBC 708.3

THE REQUIRED FIRE SEPARATION BETWEEN THE UNITS HAS NOT BEEN MAINTAINED.

CASE NO: CE13080252

CASE ADDR: 2500 E COMMERCIAL BLVD

OWNER: ALTO PROPERTY MANAGEMENT LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:
1. INTERIOR RENOVATIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2010) 105.4.4

THIS COMMERCIAL SPACE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. PLUMBING FIXTURES INSTALLED WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS COMMERCIAL SPACE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL WIRING AND DEVICES INSTALLED WITHOUT THE REQUIRED ELECTRICAL PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.11

THIS COMMERCIAL SPACE HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE MECHANICAL SYSTEM IS BEING ALTERED WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

CASE NO: CE15011800

CASE ADDR: 229 S FTL BEACH BLVD OWNER: EL-AD FL BEACH CR LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF AN AWNING DISPLAYING SIGNAGE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.8

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF AN ALUMINUM AWNING STRUCTURE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15120488
CASE ADDR: 5501 NE 25 AVE
OWNER: ATLANTIC LOFT LLC

INSPECTOR: BOBBY MASULA

VIOLATIONS: FBC (2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT

IS NOT LIMITED TO:

1. ALTERATIONS OF THE POOL DECK AREA WHERE A WALL AND WOOD FENCE WERE REMOVED AND AN ALUMINUM FENCE WAS INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY.

FBC(2014) 105.3.1.4.5

THIS PROPERTY HAS BEEN ALTERED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. AN ALUMINUM FENCE INSTALLED WITHIN FIVE FEET OF THE POOLS WATER EDGE WHICH REQUIRES AN ELECTRICAL BONDING AND THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

._____

CASE NO: CE14031507
CASE ADDR: 416 SW 11 CT

OWNER: REYNOLDS, STUART L

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

- 1. THE PROPERTY OWNER HAS CONVERTED THIS SINGLE FAMILY HOUSE INTO A DUPLEX RENTING OUT THE BACK AND FRONT TO TWO DIFFERENT FAMILIES. THEY HAVE ENCLOSED THE CARPORT AND HALLWAY LEADING TO ONE PART OF THE HOUSE TO CREATE THE NEW FLOOR PLAN.
- 2. THEY HAVE ADDED ELECTRIC OUTLETS AND PLUMBING FIXTURES IN THE ENCLOSED CARPORT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THE CARPORT HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION CLASS U (UTILITY) TO R-3 (LIVING SPACE) WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

REMEDIAL ACTION: SEE FBC (2010) 105.1 AND FBC (2010) 111.4) THE BUILDING OR PORTIONS THEREOF IS BEING USED OR OCCUPIED IN VIOLATION OF THE PROVISIONS OF THIS CODE SHALL STOP BEING USE OR THE OCCUPANCY DISCONTINUED AND THE BUILDING OR PORTION THEREOF VACATED IN 60 DAYS, AND SUCH BUILDING OR PORTION THEREOF SHALL BE MADE TO COMPLY WITH THE REQUIREMENTS OF THIS CODE BY REMOVING THE VIOLATION OR OBTAINING A C.O. FOR THE CHANGE OF USE BY ISSUING THE NECESSARY PERMITS AND PASSING ALL THE REQUIRED INSPECTIONS.

CASE NO: CE16020557 CASE ADDR: 812 SW 15 AV

OWNER: SCHUMANN, MICHAEL

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ILLEGALLY ALTERED AND CONSTRUCTION WORK ILLEGALLY PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. INTERIOR REMODEL OF INTERIOR LIVING AREAS.
- 2. REMODELED KITCHEN.
- 3. REMODELED BATHROOM AND TILED WET AREAS.
- 4. INSTALLED GATE AT FRONT ENTRY DOOR.
- 5. WOOD DECK AT BACK YARD.
- 6. PERMANENT CANOPY ATTACHED TO WALL AT FRONT WINDOW.

FBC(2014) 105.3.1.4.4

THE FOLLOWING DESCRIBED WORK REQUIRES A PLUMBING PERMIT AND INSPECTIONS:

- 1. REPLACED KITCHEN SINK WITH FIXTURES.
- 2. REPLACED BATHROOM VANITIES
- 3. REPLACED BATHROOM FIXTURES FOR SINKS AND SHOWERS.
- 4. REPLACED TOILETS.
- 5. NEW SPRINKLER MANIFOLD.
- 6. NEW WASTE LINES AND CLEANOUTS

FBC(2014) 105.3.1.4.5

THE FOLLOWING DESCRIBED WORK REQUIRES AN ELECTRICAL PERMIT AND INSPECTIONS:

- 1. REPLACED KITCHEN FIXTURES.
- 2. REPLACED BATHROOM FIXTURES.
- 3. REPLACED OUTLETS, GFI'S AND SWITCHES.
- 4. REPLACED LIGHTING FIXTURES.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15040769

CASE ADDR: 409 N VICTORIA PARK RD

OWNER: STEWART, SCOTT HABAYEB, ZIAD

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO: 1. PERGOLA BUILT ON THE

FRONT OF THE PROPERTY.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE15121013 CASE ADDR: 1633 SW 9 AV

OWNER: BERRY, TIMOTHY &

FOSTER, ANDREW L

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. POOL HEATER INSTALLATION.

2. OUTDOOR SECURITY CAMERAS INSTALLATION.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE15071410 CASE ADDR: 2427 NE 8 ST

OWNER: JAMES, GORDON D & JUSTINE

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. CARPORT WAS ENCLOSED AND CONVERTED INTO A

GARAGE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE15101042
CASE ADDR: 1815 SW 4 ST
OWNER: TRUESDALE, ANDREW
INSPECTOR: FRANK ARRIGONI

VIOLATIONS: FBC (2014) 105.1

INSPECTOR RALPH RILES REPORTED TO ME THAT DURNING AN INSPECTION FOR REROOF AT THIS LOCATION FOR RENEWED PERMIT 06023197 HE FOUND WHAT APPEARED TO BE A SMALL ADDITION BUILT W/O PERMIT. AFTER A REVIEW OF THE PERMIT HISTORY, PHOTOS FROM BCPA'S WEB SITE AND A SITE VISIT, I HAVE DETERMEND THIS:

1. STRUCTURE WAS BUILT W/O PERMITS. THE WORK INCLUDES ELECTRICAL AND PLUMBING WORK.

FBC (2014) 110.6

FBC(2014) 110.6

APPROVAL REQUIRED. NO WORK SHALL BE DONE ON ANY

PART OF A BUILDING OR STRUCTURE OR ANY,

ELECTRICAL, MECHANICAL OR PLUMBING INSTALLATION BEYOND THE POINT INDICATED HEREIN ABOVE FOR EACH SUCCESSIVE INSPECTION UNTIL SUCH INSPECTION HAS BEEN MADE AND THE WORK APPROVED AND THE INSPECTOR

HAS SO INDICATED ON THE PERMIT CARD OR AN

INSPECTION RECORD PAD AT THE JOB SITE WHICH HAS

BEEN APPROVED BY THE BUILDING OFFICIAL.